

ASS. REC. BY:

REF:

C72/ 22001329/ke

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

11/22

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGZ 9382 T

Yr Regn:

11. 07

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toy Axiom

c.c

1496

Colour

n. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

398403

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NZE141

C052522

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Premio

205/55R16

R: Tundra

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

4

mm

L/Bal.

3

mm

L/Bal.

4

mm

D.O.A.

20/1/22

D.O.I.

14/2/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S RT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

15/12 11:00 89000: Car

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

NGS MOTORSPORT PTE LTD

Blk 10 Ang Mo Kio Industrial Park 2A #02-01 AMK AutoPoint Singapore 568047

Tel :9695 5547 Fax: 6481 5727 e-mail : evelynnstrading@gmail.com

Reg No: 201812604N

14/02/2022

China Taiping Ins (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Attn: Motor Claims Dept

*Not Notified
Call by \$900k
Repair After Rain
2 days*

RE: Accident On 20/01/22@16:30Hrs
Along Gambas Ave
Involving SGZ9382T & GBG8105T
Claims against SGZ9382T (China Taiping)

We submit herewith our direct claim estimate quotation as follow:-

Replacement parts - Axio

- | | |
|----|---------------------|
| 1 | Frt Bumper |
| 1 | Frt Fender LH |
| 1 | Side Retainer LH |
| 14 | Clps, fender lining |

<i>Br/ingem</i>	\$	689.90	✓
	\$ <i>R</i>	450.60	X
	\$ <i>nn</i>	38.00	✓
<i>nn</i>	\$	5.50	X
	\$	77.00	
	\$	1,255.50	
Less 25%	\$	(313.88)	

To remove frt damaged parts with all necessary components/
attachments, repair/reshape dented body panel
Replace/reposition damaged parts, refit align into Refix all
necessary components/attachment.

\$ 500.00 *2cd*

Spray Painting - Rear Bumper, Fender RH

\$ 500.00 *400k*

\$ 1,941.62

Any other parts which necessitate repair or renewal will incur additional charged.
Please contact our Ms Evelyn @HP96955547 to arrange for survey. Thank you

Yours faithfully.

NGS MOTORSPORT PTE LTD
EVELYN NG

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: