

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001330/KQF3N2**Date:** 12/05/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00015382200	
Claimant Vehicle No :	SND7036P	Insured Vehicle No :	SNC5641K	
Date of Loss:	10/02/2022	Nature of Claim:	TP	Claim No: SNM22D201016/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SND7036P		Engine No:	L15B6021021
Make & Model:	HONDA SHUTTLE, 1.5 (A)		Chassis No:	GK82100863
Reg. Date:	20/01/2022 (Man. Year: 2019)		Odometer:	2951 km
Colour:	Metallic Red			
Engine Capacity:	1496 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,447.20	5,163.60	2,283.60	30.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,120.00	1,510.00	610.00	28.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	9,567.20	6,673.60	2,893.60	30.25
+ GST 7.00/7.00% (\$\$)	669.70	467.15	202.55	30.24
Nett Amount (\$\$)	10,236.90	7,140.75	3,096.15	30.24

INSPECTION

Date of Assignment:	11/02/2022		
Date Inspected:	11/02/2022	Inspected At:	9A SERANGOON NORTH AVE 5 SINGAPORE 554500 REPAIRER: OPTIMA WERKZ PTE LTD
Estimated Period of Repair:	6.0 days		

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 May 2022)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SND7036P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,020.10 FL	*1,020.10 FL
2	1		*REAR TAILGATE SHUTTLE EMBLEM	Necessary	52.90 FL	*52.90 FL
3	1		*REAR TAILGATE HONDA EMBLEM	Not Necessary	35.70 FL	*- FL
4	1		*REAR TAILGATE OUTER GARNISH COVER	Mtg Cracked	363.30 FL	*363.30 FL
5	1		*REAR TAILGATE INNER TRIM BOARD	Mtg Cracked	301.60 FL	*301.60 FL
6	1		*REAR TAILGATE INNER LOCK	Dented	184.50 FL	*184.50 FL
7	1		*REAR TAILGATE HANDLE COVER	Dented	34.80 FL	*34.80 FL
8	1		*REAR TAILGATE LAMP LH	Mtg Cracked	349.80 FL	*349.80 FL
9	1		*REAR TAILGATE LAMP RH	Mtg Cracked	349.80 FL	*349.80 FL
10	1		*REAR WINDSCREEN MOULDING	Necessary	96.60 FL	*96.60 FL
11	1		*REAR BUMPER SIDE BRACKET LH	Serviceable	38.60 FL	*- FL
12	1		*REAR BUMPER SIDE BRACKET RH	Serviceable	38.60 FL	*- FL
13	1		*REAR BUMPER TOWING COVER	Dented	32.40 FL	*32.40 FL
14	1		*REAR BUMPER TOP CHROME MOULDING	Necessary	128.30 FL	*128.30 FL
15	1		*REAR BUMPER REFLECTOR LH	Serviceable	49.60 FL	*- FL
16	1		*REAR BUMPER REFLECTOR RH	Cracked	49.60 FL	*49.60 FL
17	1		*REAR TAIL LAMP LH	Serviceable	393.60 FL	*- FL
18	1		*REAR TAIL LAMP RH	Serviceable	393.60 FL	*- FL
19	1		*REAR END PANEL	Bent	451.80 FL	*451.80 FL
20	1		*REAR END PANEL UPPER COVER	Buckled	103.60 FL	*103.60 FL
21	1		*REAR FLOOR PANEL	Repair	938.00 FL	*- FL
22	1		*REAR FLOOR PANEL TOOLBOX TRAY	Mtg Distorted	225.50 FL	*225.50 FL
23	1		*REAR FLOOR PANEL TOOLBOX UPPER BOARD	Serviceable	333.60 FL	*- FL
24	1		*REAR FENDER INNER TRIM BOARD LH	Mtg Cracked	361.20 FL	*361.20 FL
25	1		*REAR FENDER INNER TRIM BOARD RH	Mtg Cracked	361.20 FL	*361.20 FL
26	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
27	1		*REAR TAILGATE INNER TRIM CLIPS	Necessary	50.00 FS	*50.00 FS
28	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
29	1		*REAR BUMPER REVERSE SENSOR	Serviceable	300.00 FS	*- FS
30	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*30.00 FS
31	1		*REAR END PANEL UPPER COVER CLIPS	Necessary	40.00 FS	*40.00 FS
32	1		*REAR FENDER INNER TRIM BOARD CLIPS LH	Necessary	60.00 FS	*60.00 FS
33	1		*REAR FENDER INNER TRIM BOARD CLIPS RH	Necessary	60.00 FS	*60.00 FS
34	1		*REAR BUMPER	Bent	1,376.56 FS	*1,260.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,784.86	6,057.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,337.66	893.40
Total Parts (\$\$)	7,447.20	5,163.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,REPLACE,REFIX & READJUST REAR ACCIDENT AREAS & ETC	New	700.00	600.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE,REAR BUMPER,REAR END PANEL & ETC	New	700.00	600.00
3	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	100.00	50.00
4	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS,REAR WINDSCREEN MOULDING,REAR WINDSCREEN SEALANT & ETC.TO EFFECT REPLACE OF REAR TAILGATE	New	150.00	120.00
5	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC.BACK TO ORIGINAL OPERATIONS	New	120.00	60.00
6	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	20.00
7	TO TUFF KOTE & UNDERSEAL MATERIALS	New	150.00	60.00
8	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	120.00	0.00
Gross Labour Cost (S\$)			2,120.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >