



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 736A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT FENDER LH	DENTED	588.80	588.80
1	FRT FENDER SHIELD LH	SERVICEABLE	164.70	-
1	FRT FENDER BLUE-DRIVE LG	NECESSARY	26.60	26.60
1	FRT WHEEL CAP LH	SCRATCHED	346.40	346.40
1	HEADLAMP LH	SERVICEABLE	1,993.65	-
1	FRT BUMPER	DENTED	430.90	430.90
1	FRT BUMPER UPPER MOULDING	SERVICEABLE	368.50	-
1	FRT BUMPER SIDE BRACKET LH	NECESSARY	35.00	35.00
10	FRT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	DAYLIGHT LH	SERVICEABLE	642.50	-
1	DAYLIGHT GRILLE LH	SCRATCHED	93.45	93.45
	LESS 20% DISCOUNT		-942.50	-308.63
			3,770.00	1,234.52
	<u>LABOUR</u>			
	PANEL BEATING.		800.00	700.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	CHECK LIGHTINGS.		60.00	30.00
	TUFF KOTE.		60.00	30.00
	WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
			1,640.00	1,260.00
	GRAND TOTAL		5,410.00	2,494.52
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,000.00

Report Ref No. NS/INC22001332/Vqcn2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.