

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3036C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FENDER LH	DENTED	588.80	588.80
1	FRONT FENDER EMBLEM	NECESSARY	26.60	26.60
1	FRONT BUMPER SIDE BRACKET LH	NECESSARY	35.00	35.00
1	FRONT BUMPER	TO REPAIR SEE LABOUR	430.90	-
1	LH SIDE ROCKER GARNISH	TO REPAIR SEE LABOUR	290.00	-
1	FRONT DOOR LH	DENTED	1,797.20	1,797.20
1	FRONT DOOR WING MIRROR LH	SERVICEABLE	1,391.70	-
1	FRONT DOOR OUTER MOULDING LH	SCRATCHED	110.10	110.10
1	LH WHEEL CAP FRT	SCRATCHED	364.40	364.40
	LESS 20% DISCOUNT		-1,006.94	-584.42
			4,027.76	2,337.68
	NETT ITEMS			
1	FRONT DOOR COMFORT STICKER (N)	NECESSARY	75.00	75.00
1	REAR DOOR COMFORT APP (N)	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-15.50	-15.50
			139.50	139.50
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND LH SIDE ROCKER GARNISH.		700.00	700.00
	SPRAY PAINTING CHARGE.		800.00	750.00
	REMOVE/REFIX DOOR PARTS.		120.00	60.00
	CHECK WIRING.		60.00	30.00
			1,680.00	1,540.00
	GRAND TOTAL		5,847.26	4,017.18





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,200.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC22001333/Vqcn2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**