

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22001339/APA3Q2**Date:** 22/09/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900170865-01
Claimant Vehicle No :	SKW979A	Insured Vehicle No :	SFM338L
Date of Loss:	10/02/2022	Nature of Claim:	TP
		Claim No:	2006161586SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW979A	Engine No:	4J11BA1058
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Chassis No:	GF7W0601476
Reg. Date:	21/08/2019 (Man. Year: 2019)	Odometer:	37238 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,410.43	4,402.03	20,008.40	81.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,740.00	1,530.00	3,210.00	67.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,150.43	5,932.03	23,218.40	79.65
Approved Total (Overridden) (S\$)		4,700.00		
(S\$)	29,150.43	4,700.00	24,450.43	83.88
+ GST 7.00/7.00% (S\$)	2,040.53	329.00	1,711.53	83.88
Nett Amount (S\$)	31,190.96	5,029.00	26,161.96	83.88
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		5,665.45		

INSPECTION

Date of Assignment:	11/02/2022	Ryder Auto Pte Ltd (HQ)
Date Inspected:	11/02/2022 Inspected At:	2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit
Estimated Period of Repair:	4.0 days	Singapore 417921

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,323.20 FL	*980.00 FL
2	10		*REAR BUMPER CLIPS	No	40.00 FS	*40.00 FS
3	2		*REAR BUMPER SCREW MIDDLE	Not Necessary	10.00 FS	*- FS
4	1		*REAR BUMPER LOWER DIFFUSER	Deformed	480.10 FL	*380.00 FL
5	2		*REAR BUMPER O/S & N/S RETAINER	Necessary	168.00 FL	*168.00 FL
6	2		*REAR BUMPER O/S & N/S RETAINERS MIDDLE	Not Necessary	188.40 FL	*- FL
7	1		*REAR BUMPER O/S & N/S REFLECTOR	O/S Cracked	260.80 FL	*130.40 FL
8	2		*REAR O/S & N/S STAY	Not Necessary	342.40 FL	*- FL
9	2		*REAR O/S & N/S WHEEL ARCH (BUMPER)	Not Necessary	420.30 FL	*- FL
10	1		*REAR TAIL GATE	Dented	1,580.60 FL	*989.00 FL
11	1		*REAR TAIL GATE O/S & N/S REFLECTOR	Not Necessary	1,150.60 FL	*- FL
12	1		*REAR TAIL GATE WEATHERSTRIP	Cut	255.30 FL	*255.30 FL
13	1		*REAR TAIL GATE OUTLANDER EMBLEM	Necessary	130.70 FL	*75.00 FL
14	1		*REAR TAIL GATE MVE EMBLEM	Necessary	86.60 FL	*86.60 FL
15	1		*REAR TAIL GATE C&C EMBLEM	Necessary	78.20 FL	*78.20 FL
16	1		*REAR TAIL GATE EMBLEM	Necessary	65.80 FL	*65.80 FL
17	1		*REAR TAIL GATE INNER TRIM (LOWER)	Cracked	342.40 FL	*342.40 FL
18	1		*REAR TAIL GATE INNER TRIM CLIPS (16 PCS)	Necessary	80.00 FS	*30.00 FS
19	1		*REAR TAIL GATE LOCK (UPPER)	Damaged	577.10 FL	*285.00 FL
20	1		*REAR TAIL GATE HANDLE	Not Necessary	242.60 FL	*- FL
21	1		*REAR TAIL GATE BUZZER	Cracked	140.40 FL	*140.40 FL
22	2		*REAR O/S & N/S TAIL LAMP	Not Necessary	1,595.00 FL	*- FL
23	1		*REAR KEYLESS ANTENNA	Not Necessary	135.00 FL	*- FL
24	1		*REAR END PANEL	Repair	845.70 FL	*- FL
25	1		*REAR END PANEL INNER TRIM	Deformed	220.60 FL	*220.60 FL
26	1		*REAR END PANEL INNER TRIM CLIPS (6 PCS)	Necessary	30.00 FS	*10.00 FS
27	12		*REAR O/S & N/S FENDER INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS
28	2		*REAR O/S & N/S FENDER INNER TRIM	Not Necessary	1,300.60 FL	*- FL
29	1		*REAR REVERSE CAMERA	Damaged	600.00 FS	*300.00 FS
30	2		*REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
31	1		*REAR REG NO PLATE	Not Necessary	45.00 FS	*- FS
32	1		*REAR REG NO PLATE BRACKET	Not Necessary	29.00 FS	*- FS
33	1		*FRONT BUMPER	Not Necessary	1,234.70 FL	*- FL
34	10		*FRONT BUMPER CLIPS	Not Necessary	40.00 FS	*- FS
35	2		*FRONT BUMPER O/S & N/S RETAINER	Not Necessary	166.40 FL	*- FL
36	1		*FRONT BUMPER LOWER DIFFUSER	Not Necessary	665.70 FL	*- FL
37	1		*FRONT BONNET	Not Necessary	1,305.60 FL	*- FL
38	1		*FRONT BONNET OUTLANDER WORDING	Not Necessary	90.50 FL	*- FL
39	1		*FRONT GRILLE (UPPER)	Not Necessary	684.10 FL	*- FL
40	1		*FRONT GRILLE (UPPER) BASE	Not Necessary	334.30 FL	*- FL
41	1		*FRONT GRILLE LOWER	Not Necessary	455.40 FL	*- FL
42	2		*FRONT GRILLE LOWER O/S & N/S CHROME GARNISH	Not Necessary	265.20 FL	*- FL
43	1		*FRONT REINFORCEMENT	Not Necessary	682.30 FL	*- FL
44	1		*FRONT REINFORCEMENT LOWER GUARD	Not Necessary	224.50 FL	*- FL
45	2		*FRONT N/S & O/S STAY	Not Necessary	162.20 FL	*- FL
46	2		*FRONT N/S & O/S HEAD LAMP	Not Necessary	4,264.20 FL	*- FL
47	2		*FRONT O/S & N/S WHEEL ARCH (FENDER)	Not Necessary	438.20 FL	*- FL
48	6		*FRONT O/S & N/S WHEEL ARCH (BUMPER)	Not Necessary	275.60 FL	*- FL
49	1		*FRONT UNDERCOVER	Not Necessary	320.30 FL	*- FL
50	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	165.20 FL	*- FL
51	1		*FRONT SUPPORT PANEL	Not Necessary	1,230.30 FL	*- FL
52	1		*FRONT N/S FOG LAMP	Not Necessary	449.20 FL	*- FL
53	1		*FRONT N/S FOG LAMP GARNISH	Not Necessary	108.20 FL	*- FL
54	1		*FRONT N/S RADIATOR SIDE GARNISH (BLACK)	Not Necessary	150.20 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	1		*RADIATOR (NPA)	Not Necessary	0.00 FL	*- FL
56	1		*COOLENT	Not Necessary	80.00 FS	*- FS
57	1		*CONDENSER (NPA)	Not Necessary	0.00 FL	*- FL
58	1		*REAR REG NO PLATE	Bent	45.00 FS	*45.00 FS
59	1		*FRONT REG NO PLATE BRACKET	Not Necessary	29.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$)	26,970.70
					- List Item Discount on L Items 10.00/10.00% (\$)	4,821.70
						2,560.27
					Total Parts (\$)	4,402.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING	New	2,000.00	500.00
2	TO SPRAY PAINTING	New	1,600.00	600.00
3	TO REMOVE & REFIT REAR WINDSCREEN	New	160.00	120.00
4	TO REMOVE & REPLACE REAR REVERSE SENSOR	New	80.00	50.00
5	TO REMOVE & REPLACE REAR REVERSE CAMERA	New	80.00	50.00
6	TO REMOVE & REPLACE REAR TAIL GATE FITTINGS	New	100.00	80.00
7	TO REMOVE AND REPLACE CONDENSER & RADIATOR	New	140.00	0.00
8	TO REMOVE AND REFIT REAR UPHOLSTERY TO FACILITATE REPAIR	New	150.00	60.00
9	TO CHECK FOR FAULT CODE AND RESETTNG	New	250.00	0.00
10	TO CHECK WIRING	New	80.00	30.00
11	TO RESEAL ANTI RUST	New	100.00	40.00
Gross Labour Cost (\$\$)			4,740.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >