

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS3/SMO22001340/Uvf3e2	
	50 RAFFLES PLAC TOWER SINGAPO		Date:	25/02/2022		
				Code:	SMO	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBC 5330A	Veh. Inspected	t	SLS 9880A	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2200536/GPL	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		11/02/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HONDA HRV DX (A)	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	JHMRU1810GX202962	Colour		WHITE	
	Odometer	92396 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	DUNLOP		7 mm	
	L/H Front Tyre	215/60 R16	DUNLOP		7 mm	
	R/H Rear Tyre	215/60 R16	DUNLOP		7 mm	
	L/H Rear Tyre	215/60 R16	DUNLOP		7 mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5.	5. General Information					
	Accident Date	09/02/2022	Inspect Date /	Time	14/02/2022 (11:00 AM)	
	Survey held at	HUAT AUTOMOBILE AIR-CON	SERVICE			
	3007 UBI ROAD 1, #01-404, KAMPONG UBI INDUSTRIAL ESTATE, SINGAPORE 408701					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					

Report Ref No. CS3/SMO22001340/Uvf3e2

Inspected By

CHUA KANG SENG Licensed Appraiser K.K.LAU CPT(RET)

 ${\tt BEng(Hons),B.Bus,MBA,PEng,PE,\,MInstAEA,MASME,MIRTE}$

REGD Auto Consultant-SAE, Licensed Appraiser