

1	of 2 ?	100%	Find   Next
---	--------	------	-------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

<b>Affiliated to Federation Internationale Des Experts En Automobile</b>			
SOMPO INSURANCE SINGAPORE PL		Ref:	CS3/SMO22001340/Uvf3e2
50 RAFFLES PLACE #03-03 SINGAPORE LAND		Date:	25/02/2022
TOWER SINGAPORE 048623		Code:	SMO
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>			
<b>Insured Veh.</b>	GBC 5330A	<b>Veh. Inspected</b>	SLS 9880A
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	CMTD2200536/GPL	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	GRACE TEO	<b>Assign Date</b>	11/02/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
<b>Make &amp; Model</b>	HONDA HRV DX (A)	<b>c.c</b>	1496
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	JHMRU1810GX202962	<b>Colour</b>	WHITE
<b>Odometer</b>	92396 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>			
	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	215/60 R16	DUNLOP	7 mm
<b>L/H Front Tyre</b>	215/60 R16	DUNLOP	7 mm
<b>R/H Rear Tyre</b>	215/60 R16	DUNLOP	7 mm
<b>L/H Rear Tyre</b>	215/60 R16	DUNLOP	7 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
<b>5. General Information</b>			
<b>Accident Date</b>	09/02/2022	<b>Inspection Date</b>	14/02/2022
<b>Survey held at</b>	HUAT AUTOMOBILE AIR-CON SERVICE 3007 UBI ROAD 1, #01-404, KAMPONG UBI INDUSTRIAL ESTATE, SINGAPORE 408701		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	