

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG22001341/KPA3Q2**Date:** 04/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100496068
<b>Claimant Vehicle No :</b>	SHD252Z	<b>Insured Vehicle No :</b>	SLJ9788G
Date of Loss:	10/02/2022	Nature of Claim:	TP
		Claim No:	4549727528SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD252Z</b>		
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C002698
Reg. Date:	03/11/2015 (Man. Year: 2015)	Chassis No:	VF1ABL15AUC282187
Colour:	Metallic White/Red	Odometer:	626503 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 8 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 8 mm	Rear Right Side:	Sailun 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,846.07	9,122.00	1,724.07	15.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,580.00	1,530.00	9,050.00	85.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>21,426.07</b>	<b>10,652.00</b>	<b>10,774.07</b>	<b>50.28</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,300.00</b>		
<b>(S\$)</b>	21,426.07	7,300.00	14,126.07	65.93
<b>+ GST 7.00/7.00% (S\$)</b>	1,499.82	511.00	988.82	65.93
<b>Nett Amount (S\$)</b>	<b>22,925.89</b>	<b>7,811.00</b>	<b>15,114.89</b>	<b>65.93</b>
<b>+ Loss of Use (6.0 x S\$50.00/day) (S\$)</b>		300.00		
<b>+ Car Rental (6.0 x S\$81.13/day) (S\$)</b>		486.78		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>8,605.23</b>		
<b>Global Sum Settlement (S\$)</b>		<b>8,600.00</b>		

INSPECTION

Date of Assignment:	11/02/2022		
Date Inspected:	11/02/2022	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	4.0 days		

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Bent	747.20 FL	*747.20 FL
2	1		*BUMPER ABSORBER FRT	Missing	394.68 FL	*394.68 FL
3	1		*BUMPER RETAINER FRT LH	Distorted	101.40 FL	*101.40 FL
4	1		*BUMPER SPONGE FRT	Serviceable	10.70 FL	*- FL
5	1		*BUMPER RETAINER FRT RH	Distorted	101.40 FL	*101.40 FL
6	1		*BUMPER SUPPORT FRT	Serviceable	10.70 FL	*- FL
7	1		*BUMPER UNDERTRAY FRT	Cracked	292.50 FL	*292.50 FL
8	1		*BUMPER SPOILER FRT	Distorted	344.70 FL	*344.70 FL
9	1		*BUMPER GRILLE LOWER FRT	Distorted	147.00 FL	*147.00 FL
10	1		*BUMPER BEAM FRT	Bent	663.70 FL	*663.70 FL
11	1		*BONNET	Bent	1,312.70 FL	*1,312.70 FL
12	1		*BONNET INSULATOR	Serviceable	294.30 FL	*- FL
13	1		*BONNET HINGE LH	Distorted	237.40 FL	*237.40 FL
14	1		*BONNET HINGE RH	Repair	237.40 FL	*- FL
15	1		*BONNET LOCK	Bent	152.80 FL	*152.80 FL
16	1		*RADIATOR GRILLE	Cracked	969.90 FL	*969.90 FL
17	1		*RADIATOR GRILLE BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
18	1		*RADIATOR GRILLE FRAME	Cracked	686.00 FL	*686.00 FL
19	1		*FRAME FULL SUPPORT PANEL	Cracked	592.70 FL	*592.70 FL
20	1		*FENDER PANEL FRT LH	Repair	437.10 FL	*- FL
21	1		*FENDER PANEL FRT RH	Repair	437.10 FL	*- FL
22	1		*A/C CONDENSER	Bent / Punctured	1,537.80 FL	*1,537.80 FL
23	1		*HEADLAMP LH	Mtg Cracked	743.60 FL	*743.60 FL
24	1		*HEADLAMP RH	Mtg Cracked	743.60 FL	*743.60 FL
25	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS
26	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS
27	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
28	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
29	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
30	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
31	1		*BUMPER CLIP FRT	Necessary	85.00 FS	*66.00 FS
32	1		*BUMPER RETAINER CLIP FRT	Not Necessary	70.00 FS	*- FS
33	1		*BUMPER GRILLE LOWER CLIP	Not Necessary	70.00 FS	*- FS
34	1		*LICENSE PLATE WITH HOLDER FRT	Missing	120.00 FS	*45.00 FS
35	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*- FS
36	1		*SET RADIATOR GRILLE SCREW	Necessary	16.00 FS	*16.00 FS
37	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>11,988.24</b>	<b>10,121.44</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	1,142.17	999.44
<b>Total Parts (\$)</b>	<b>10,846.07</b>	<b>9,122.00</b>

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	880.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	6,000.00	600.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
			<b>Gross Labour Cost (\$)</b>	<b>10,580.00</b>
				<b>1,530.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >