

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III22001367/UGA3Q2**Date:** 10/08/2022**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0006133_02

Claimant Vehicle No : GBB528K **Insured Vehicle No :** PC218J

Date of Loss: 11/02/2022 Nature of Claim: TP Claim No: MFL2022D0000998

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBB528K**

Make & Model: NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD Turbo (A) Engine No: ZD30168515K

Reg. Date: 28/06/2008 (Man. Year: 2008) Chassis No: JN1SC2F24Z0800242

Colour: Silver Odometer: 330109 km

Engine Capacity: 2953 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 165 R13 (D)

Front Left Side: Yokohama 6 mm Rear Left Side: Condor 6/6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Condor 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,070.10	3,355.22	9,714.88	74.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,150.00	2,280.00	3,870.00	62.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,220.10	5,635.22	13,584.88	70.68
Approved Total (Overridden) (S\$)		4,500.00		
Nett Amount (S\$)	19,220.10	4,500.00	14,720.10	76.59
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,007.45		

INSPECTION

Date of Assignment: 14/02/2022

Date Inspected: 14/02/2022 Inspected At:

Estimated Period of Repair: 5.0 days

Choo Motor Spray Painter (HQ)
1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki
Bukit
Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Jul 2022)	
Parts:	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD Turbo (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB528K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	1,860.00 F	*1,399.00 FL
2	2		*REAR TAILGATE LOCK LATCHES	Repair	760.00 F	*- FL
3	2		*REAR TAILGATE LOCK LOWER L BRACKETS	Repair	360.00 F	*- FL
4	2		*REAR TAILGATE LOCK LOWER L BRACKET RUBBERS	Serviceable	240.00 F	*- FL
5	2		*TAILLAMPS	Cracked	900.00 F	*580.00 FL
6	2		*TAILLAMP HOUSING PANELS	Not Necessary	360.00 F	*- FL
7	1		*REAR LICENCE PLATE BRACKET	Bent	345.00 F	*154.00 FL
8	1		*REAR LICENCE PLATE LAMP	Broken	165.00 F	*125.00 FL
9	1		*REAR EXHAUST	Not Necessary	1,250.00 F	*- FL
10	1		*REAR EXHAUST MOUNTING	Not Necessary	85.00 F	*- FL
11	1		*REAR END PANEL	Dented / Bent	685.10 F	*588.60 FL
12	1		*REAR SPARE TYRE CARRIER & CHAIN	Damaged	680.00 F	*399.20 FL
13	1		*DROPSIDE GATE PANEL N/S	Repair	2,290.00 F	*- FL
14	1		*DROPSIDE GATE PANEL O/S	Repair	2,290.00 F	*- FL
15	1		*SET REAR TAILGATE 70KM/H & 13PAX STICKER	Necessary	50.00 FS	*20.00 FS
16	1		*SET REAR REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
17	1		*REAR LICENCE PLATE	Bent	50.00 FS	*14.00 FS
18	1		*REAR STEP WOODEN	Cracked	400.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,070.10	3,679.80
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	324.58
Total Parts (\$\$)	13,070.10	3,355.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	100.00	50.00
3	TO DISMANTLE & REPLACED REAR CARGO DECK	New	800.00	350.00
4	TO SPRAY RUST PROOFING	New	200.00	60.00
5	LABOUR FOR PANEL BEATING & REPLACED PARTS }	New	2,200.00	1,000.00
6	TO STRAIGHTEN & REALIGN CHASSIS }	New	1,000.00	0.00
7	TO PUTTY & SPRAY PAINTING	New	1,800.00	800.00
Gross Labour Cost (\$\$)			6,150.00	2,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >