5/5/22, 9:29 AM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CC3/AIG22001368/ATY3N2

AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Date: 05/05/2022

**REFERENCE** 

Insured/Claimant: NG SAI KIN (WU SHIJIAN) Policy No: 1800129481-03

Date of Loss: 23/01/2022 Nature of Claim: OD Claim No: 6547138477SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMF1243Z

Make & Model: AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A) Engine No: CZE802055

Reg. Date: 29/10/2018 (Man. Year: 2018) Chassis No: WAUZZZ8V1J1082735

Colour: Red Odometer: 28114 km

Engine Capacity: 1395 cc
Market Value/New Car Price: \$\$94,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,421.00	1,045.36	3,375.64	76.35
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,152.00	2,602.00	1,550.00	37.33
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Gross T	otal (S\$)	8,573.00	3,647.36	4,925.64	57.46
+ GST 7.00/7.0	00% (S\$)	600.11	255.32	344.79	57.45
Nett Amo	ount (S\$)	9,173.11	3,902.68	5,270.43	57.46

INSPECTION

Date of Assignment: 14/02/2022

Premium Automobiles Pte Ltd (UBI)

Date Inspected: 11/02/2022 Inspected At: 55 Ubi Road 1 Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

#### **REPAIR DETAILS**

# **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,944.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	201.00 FS	*- FS
3	1		*REAR BUMPER ADAPTER-LH	Not Necessary	42.00 FS	*- FS
4	2		*REAR BUMPER GUIDE SECTION-LH/RH	Not Necessary	36.00 FS	*- FS
5	1		*REAR BUMPER SPOILER-LH	Not Necessary	264.00 FS	*- FS
6	1		*REAR LIGHT REFLECTOR-LH	Not Necessary	46.00 FS	*-FS
7	1		*REAR BUMPER GUIDE SECTION LOWER-LH	Not Necessary	75.00 FS	*- FS
8	1		*REAR WHEEL HOUSING LINER-RH	Not Necessary	260.00 FS	*-FS
9	1		*ALUMINIUM RIM	Cut	1,303.00 FS	*1,042.40 FS
10	1		*SUNDRIES	Necessary	250.00 FS	*2.96 FS
F=Fra	ınchise	part. S=SpcN	lett.	-		
				Total Parts (S\$)	4,421.00	1,045.36
			Report was unsubmitted during	this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	TO REMOVE AND TRANSFER REAR PARKING AID.CHECK FUNCTION	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER.TO REPAIR LHS REAR FENDER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,400.00	750.00
3	TO RESPRAY REAR BUMPER AND LHS REAR FENDER	New	2,000.00	1,100.00
4	TO RENEW LHS REAR RIM AND CARRY OUT DIAGNOSTIC CHECK	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labour Cost (S\$)		4,152.00	2,602.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >