

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III22001369/UPA3Q2**Date:** 20/05/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MPC0002418
Claimant Vehicle No : SLC1156U **Insured Vehicle No :** SGT3107T
 Date of Loss: 11/02/2022 Nature of Claim: TP Claim No: MPC2022D0000873

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLC1156U**
 Make & Model: MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A) Engine No: P520348874
 Reg. Date: 29/04/2016 (Man. Year: 2016) Chassis No: JM6BM42A8G0333610
 Colour: Red Odometer: 90781 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,986.00	10,243.76	17,742.24	63.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,630.00	3,310.00	1,320.00	28.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,616.00	13,553.76	19,062.24	58.44
Approved Total (Overridden) (S\$)		10,500.00		
Nett Amount (S\$)	32,616.00	10,500.00	22,116.00	67.81
+ Loss of Use (10.0 x S\$60.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		11,107.45		
Global Sum Settlement (S\$)		11,100.00		

INSPECTION

Date of Assignment: 14/02/2022
 Date Inspected: 14/02/2022 Inspected At: Choo Motor Spray Painter (HQ)
 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki
 Bukit
 Singapore 417883
 Estimated Period of Repair: 8.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Apr 2022)

Parts: 143 MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLC1156U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted / Torn	1,250.00 F	*971.40 FL
2	1		*FRONT BUMPER SIDE RETAINERS	Bent	130.00 F	*130.00 FL
3	2		*FRONT BUMPER FOG LAMPS	Not Necessary	610.00 F	*- FL
4	2		*FRONT BUMPER FOG LAMP GARNISHS	N/S Grazed / O/S Missing	320.00 F	*160.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Repair	665.00 F	*- FL
6	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
7	2		*FRONT FENDERS	Dented / Bent	1,090.00 F	*701.20 FL
8	2		*FRONT FENDER INNER SHIELD	Torn	330.00 F	*330.00 FL
9	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	50.00 F	*50.00 FL
10	2		*HEADLAMPS	Cracked	5,360.00 F	*1,624.00 FL
11	1		*FRONT SUPPORT PANEL	Not Necessary	541.00 F	*- FL
12	1		*WIPER WASHER TANK	Deformed	281.00 F	*242.50 FL
13	2		*FRONT SPORTS RIMS	Bent / Warped	2,200.00 F	*2,200.00 FL
14	2		*FRONT SHOCK ABSORBERS	Bent	1,136.00 F	*721.60 FL
15	2		*FRONT LOWER ARMS	Bent	990.00 F	*909.40 FL
16	2		*FRONT KNUCKLE ARMS	Warped	1,160.00 F	*910.40 FL
17	2		*FRONT KNUCKLE ARM BEARINGS	Damaged	700.00 F	*500.00 FL
18	1		*FRONT DRIVE SHAFT	Not Necessary	1,400.00 F	*- FL
19	1		*FRONT DOOR MIRROR N/S	Repair	850.00 F	*- FL
20	1		*FRONT DOOR N/S	Bent / Warped	1,021.00 F	*1,021.00 FL
21	1		*FRONT DOOR FRAME BLACK GARNISH N/S	Necessary	80.00 F	*80.00 FL
22	1		*FRONT DOOR INNER RUBBER N/S	Necessary	112.00 F	*112.00 FL
23	1		*REAR DOOR N/S	Repair	981.00 F	*- FL
24	1		*REAR DOOR FRAME BLACK GARNISH N/S	Not Necessary	80.00 F	*- FL
25	1		*FRONT DOOR O/S	Repair	1,021.00 F	*- FL
26	1		*FRONT DOOR FRAME BLACK GARNISH O/S	Grazed	80.00 F	*80.00 FL
27	1		*FRONT DOOR INNER RUBBER O/S	Not Necessary	112.00 F	*- FL
28	1		*REAR DOOR O/S	Repair	981.00 F	*- FL
29	1		*REAR FENDER O/S	Repair	1,025.00 F	*- FL
30	1		*REAR BUMPER	Cut	1,250.00 F	*981.20 FL
31	1		*REAR BUMPER SIDE RETAINER O/S	Necessary	65.00 F	*65.00 FL
32	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
33	1		*REAR SPORT RIM O/S	Serviceable	1,100.00 F	*- FL
34	1		*TAILLAMP O/S	Scratched	915.00 F	*915.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	27,986.00	12,804.70
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	2,560.94
Total Parts (\$\$)	27,986.00	10,243.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX REAR REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX FRONT DOOR MECHANISM	New	120.00	60.00
4	TO DISMANTLE & REPLACED FRONT BOTH UNDER CARRIAGE	New	450.00	240.00
5	TO CONDUCT WHEEL ALIGNMENT	New	120.00	100.00
6	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
7	TO RESET & REPROGRAMME SYSTEM	New	150.00	60.00
8	TO REFILL AIR CON GAS	New	120.00	0.00
9	TO SPRAY RUST PROOFING	New	120.00	100.00
10	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,100.00	800.00
11	TO PUTTY & SPRAY PAINTING	New	2,200.00	1,800.00
Gross Labour Cost (\$\$)			4,630.00	3,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >