

ASS. REC. BY:

Steve

REF:

CC4/LPC 22 001373/ea3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
XX	XX

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: YN 4061C Yr Regn: 13/8/13Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: ISUZU NMR 85 c.c. 2999Colour: White A/C: Insured / Std / NI / NASp. Reading: 403690 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JAA NMR 85 HD 11 of 120Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 7.00R16R: 11BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 4 mmL/Bal. 4 mmD.O.A. 9/2/22Survey held at ASMDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 4 mmL/Bal. 4 mmD.O.I. 14/2/22

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV - 10K

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

: Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:


Transportation:

S + RS \$ _____

Photos

Others

TOTAL



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424
Main Line: 6265 0980 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C

bizSAFE₃

FROM : Alex Sim
TEL. NO. : 6265-0026 / 98154748
EMAIL : alex@asmauto.com.sg

DATE : 11-02-22

TO : Lonpac Insurance Bhd
ATTN : Motor Claim Department
TEL. NO. : 6250-7388
EMAIL : mt_claim@lonpac.com

VEHICLE NO. : YN4061C
MODEL NO. : Isuzu
CHASSIS NO. : JAANMR85HD7101720
ENGINE NO. : 4JJ1369404
LTA REG DATE : 13-08-13

CC : Evershine Projects Pte Ltd

CLAIM TYPE : Third party claim
D.O.A : 09-02-22
CLAIM REF NO. : asm/AC22011/JL

Quotation for Accident Repair

S/N	SPARE PARTS (nett)	QUANTITY	UNIT PRICE	AMOUNT
1	Rear wooden drop gate / BR	1	\$ 550.00	\$ 550.00
2	Front wooden panel / BR	1	\$ 550.00	\$ 550.00
3	Under cross beam	2	\$ 180.00	\$ 360.00
4	Under long beam / BR	1	\$ 360.00	\$ 360.00
5	Cabin hook handle / BT	1	\$ 450.00	\$ 450.00
6				\$ -
mudguard Rear LH / \$250				
SUB-TOTAL :				\$ 2,270.00

LABOUR CHARGES

- To remove wooden body deck, to replace broken wooden plank and drop gate, to knock and straighten body frame, realign wooden floor plank etc. \$ 1,400.00 1000
- To panel beat cabin rear end panel, replace cabin hook handle and realign cabin and door. \$ 1,050.00 600
- spray painting \$ 400.00 300

TOTAL LABOUR : \$ 2,850.00

GRAND TOTAL : \$ 5,120.00

Stem (LKR)
14/2/22. 11.31C

ML RL
7 days
P/P
My RL y

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: