

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001375/KVY3Q2**Date:** 11/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00156272101

Claimant Vehicle No : SLQ600L **Insured Vehicle No :** YQ3458H

Date of Loss: 07/02/2022 Nature of Claim: TP Claim No: SNM22D200883/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ600L**

Make & Model: HONDA VEZEL, 1.5 HYBRID X (A) Engine No: LEB5944350

Reg. Date: 06/06/2017 (Man. Year: 2017) Chassis No: RU31244333

Colour: Metallic Gold Odometer: 198198 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 3 mm

Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,452.68	4,969.84	3,482.84	41.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,150.00	1,350.00	54.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	10,952.68	6,119.84	4,832.84	44.12
+ GST 7.00/7.00% (\$\$)	766.69	428.39	338.30	44.12
Nett Amount (\$\$)	11,719.37	6,548.23	5,171.14	44.12

INSPECTION

Date of Assignment: 11/02/2022

Date Inspected: 15/02/2022 Inspected At: Accord Auto Services Pte Ltd (HQ)
10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point
Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Mar 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ600L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	854.10 FL	*854.10 FL
2	2		*FRONT BONNET HINGE	Distorted	100.00 FL	*100.00 FL
3	1		*FRONT BONNET LOCK	Repair	124.20 FL	*- FL
4	1		*FRONT BONNET SEAL	Serviceable	36.80 FL	*- FL
5	1		*FRONT BONNET STOPPER	Serviceable	10.90 FL	*- FL
6	1		*FRONT HEADLAMP LH	Mtg Cracked	1,999.30 FL	*1,850.00 FL
7	1		*FRONT HEADLAMP RH	Mtg Cracked	1,999.30 FL	*1,850.00 FL
8	2		*FRONT HEADLAMP LOWER BRACKET LH & RH	Cracked	68.40 FL	*68.40 FL
9	2		*FRONT HEADLAMP CHROME	No such part	280.00 FL	*- FL
10	1		*FRONT GRILLE TOP OUTER GARNISH	Cracked	434.50 FL	*421.60 FL
11	1		*FRONT GRILLE TOP RUBBER	Serviceable	194.20 FL	*- FL
12	1		*FRONT GRILLE BASE	Serviceable	301.80 FL	*- FL
13	1		*FRONT GRILLE CHROME LOWER	Serviceable	71.20 FL	*- FL
14	1		*FRONT EMBLEM H	Necessary	30.00 FL	*30.00 FL
15	1		*FRONT BUMPER	Buckled	898.30 FL	*801.70 FL
16	2		*FRONT BUMPER SIDE RETAINER	Distorted	47.80 FL	*47.80 FL
17	1		*FRONT BUMPER TOW COVER	Serviceable	18.30 FL	*- FL
18	2		*FRONT BUMPER SIDE GARNISH RH & LH	Serviceable	70.00 FL	*- FL
19	1		*FRONT FOGLAMP LH	Serviceable	280.00 FL	*- FL
20	1		*FRONT FOGLAMP RH	Serviceable	280.00 FL	*- FL
21	1		*FRONT LOWER GRILLE	Serviceable	84.20 FL	*- FL
22	1		*FRONT LH FENDER	Repair	421.10 FL	*- FL
23	1		*FRONT LH FENDER SHIELD	Serviceable	125.90 FL	*- FL
24	1		*FRONT RH FENDER	Repair	421.00 FL	*- FL
25	1		*FRONT RH FENDER SHIELD	Serviceable	125.90 FL	*- FL
26	1		*FRONT SUPPORT PANEL	Repair	526.50 FL	*- FL
27	1		*FRONT REINFORCEMENT BAR	Repair	293.40 FL	*- FL
28	1		*FRONT RADIATOR TOP COVER /GARNISH	Serviceable	61.30 FL	*- FL
29	1		*BRACE PANEL	Cracked	76.20 FL	*76.20 FL
30	1		*CAR PLATE NUMBER WITH HOLDER	Dented	50.00 FS	*45.00 FS
31	1		*SET FRONT BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
32	1		*SET FRONT BONNET INSULATOR CLIPS	Not Necessary	45.00 FS	*- FS
33	1		*SET FRONT RADIATOR CLIPS COVER /GARNISH CLIPS	Not Necessary	45.00 FS	*- FS
34	2		*SET FRONT FENDER INNER SHIELD CLIPS LH & RH	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,499.60	6,189.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,046.92	1,219.96
Total Parts (\$\$)	8,452.68	4,969.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT ON ALL AFFECTED AREA	New	1,000.00	600.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK JACK,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,000.00	500.00
3	TO CHECK WIRING SYSTEM & LIGHT	New	100.00	20.00
4	TO APPLY ANTI RUST TREATMENT	New	120.00	30.00
5	TO REMOVE /REFIX NECESSARY ATTACHMENT SUPPORT PANEL	New	280.00	0.00
Gross Labour Cost (\$\$)			2,500.00	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >