

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22001379/Vvy3e2
	8 SHENTON WAY SINGAPORE 0688		Date:	15/03/2022	
	ATTN: KOH JANIC	E		Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 9920K	Veh. Inspected		FBS 3550K
	Policy No.	VFX/P2419140	Coverage (\$)		0.00
	Claim No.	S2M03T1J	Excess (\$)		0.00
	Assign From	KOH JANICE	Assign Date		14/02/2022
2. Vehicle Particulars & Condition					
	Make & Model	HONDA ADV150A	c.c		149
	Engine No.	HIDDEN	Year of Reg.		2021
	Chassis No.	KF381008948	Colour		RED
	Odometer	-	Steering		IN ORDER
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	130/70 R13	ANGEL SCOOTE	R	6 mm
	L/H Front Tyre				mm
	R/H Rear Tyre	130/70 R13	ANGEL SCOOTE	R	6 mm
	L/H Rear Tyre				mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
5.	. General Information				
	Accident Date	08/02/2022	Inspect Date /	Time	14/02/2022 (04:12 PM)
_	Survey held at S1 MOTORING				
	BLK 3006 UBI ROAD 1 #01-386 SINGAPORE 408700				
5a.	. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM22001379/Vvy3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

Tu

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser