



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2205753

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 19/09/2022
Reference CC6/CTI22001384/Kea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. GBH 5371E
Insured Veh. YQ 3695P
Claim No. SNM22D201039/C02
Policy No. DMCVSNA00119112101
Accident Date 10/02/2022
Inspection Date 17/03/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22001384/Kea3q2 Date: 19/09/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YQ 3695P	Veh. Inspected	GBH 5371E	
Policy No.	DMCVSNA00119112101	Coverage (\$)	0.00	
Claim No.	SNM22D201039/C02	Excess (\$)	0.00	
Assign From		Assign Date	17/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTFAT35Y70K210702	Colour	BLUE	
Odometer	131702 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	WINDFORCE	2 mm	
L/H Front Tyre	195 R15X8	WINDFORCE	2 mm	
R/H Rear Tyre	155 R12X8 (D)	MILEMAX	8/8 mm	
L/H Rear Tyre	155 R12X8 (D)	MILEMAX	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/02/2022	Inspection Date	17/03/2022	
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 5371E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BENT	748.90	699.00
2	FRONT BUMPER BRACKET @\$302.00	BENT / DISTORTED	604.00	439.00
1	FRONT GRILLE	CRACKED	595.20	561.72
1	FRONT GRILLE EMBLEM	NECESSARY	70.50	70.50
2	HEAD LAMPS @\$1178.70	O/S MTG CRACKED	2,357.40	1,178.70
1	FRONT PANEL	BENT	1,194.30	1,021.20
1	FRONT PANEL DYNA EMBLEM	NECESSARY	68.40	68.40
1	N/S FRONT WING MIRROR C/W BRACKET	TO REPAIR SEE LABOUR	600.10	-
1	AIR CON COOLING COIN UNIT	HOUSING CRACKED	2,674.00	1,776.30
	LESS 25% DISCOUNT		-2,228.20	-1,453.71
			6,684.60	4,361.11
1	FRONT WINDSCREEN RUBBER (50%)(SN)	NECESSARY	369.40	184.70
	LESS 25% DISCOUNT		-92.35	-
			277.05	184.70
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	BENT	40.00	18.00
			40.00	18.00
	<u>LABOUR</u>			
	TO PUTTY & SPRAY PAINT.		700.00	520.00
	TO REMOVE & REFIX FRONT WINDSCREEN GLASS.		100.00	60.00
	TO REMOVE & REFIX FRONT DASHBOARD ASSY.		350.00	250.00
	TO REPLACE AIR-CON COOLING COIN & TOP UP GAS.		80.00	80.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF N/S FRONT WING MIRROR C/W BRACKET.		650.00	600.00
			1,880.00	1,510.00
	GRAND TOTAL		8,881.65	6,073.81



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,850.00
---	--	--	----------

Report Ref No. CC6/CTI22001384/Kea3q2

A handwritten signature in black ink, appearing to be 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBH 5371E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBH 5371E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBH 5371E

RE-INSPECTION

