

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22001386/Rqy3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 25/02/2022 SINGAPORE 068811 ATTN: KOH JANICE Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **GBF 6830B** Veh. Inspected SMT 7556H Policy No. GA182003 Coverage (\$) 0.00 Claim No. S2M03T7R Excess (\$) 0.00 **Assign Date KOH JANICE** 14/02/2022 Assign From 2. **Vehicle Particulars & Condition** TOYOTA COROLLA ALTIS 1.6 Make & Model 1598 c.c Engine No. **HIDDEN** Year of Reg. 2013 Chassis No. MR053REE104159164 Colour **GREY** 119815 KM Odometer IN ORDER Steering **IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General **Conditions of Tyres** 3. Size Make **Balance** 195/65 R15 DUNLOP 5 mm R/H Front Tyre DUNLOP L/H Front Tyre 195/65 R15 5 mm R/H Rear Tyre 195/65 R15 **DUNLOP** 5 mm 195/65 R15 DUNLOP L/H Rear Tyre 5 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. **General Information** 5. **Accident Date** 04/02/2022 **Inspect Date / Time** 15/02/2022 (11:47 AM) KING'S AUTO REPAIR & SERVICE PTE LTD Survey held at 176 SIN MING DRIVE, #02-10, SIN MING AUTOCARE, SINGAPORE 575721 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000 5b. **Estimate Days of Repair ESTIMATED NORMAL PERIOD FOR REPAIR:** 4 Working Days

Report Ref No. CS3/ASM22001386/Rgy3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser