



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 9145B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DENTED / DEFORMED	486.10	486.10
6	REAR BUMPER CLIP @\$1.50	NECESSARY	9.00	9.00
1	REAR BUMPER LOWER BRACKET	SERVICEABLE	200.00	-
1	REAR END PANEL OUTER	TO REPAIR SEE LABOUR	155.00	-
1	PARKING SENSOR	SERVICEABLE	252.00	-
	LESS 25% DISCOUNT		-275.53	-123.78
			826.57	371.32
	<b><u>LABOUR</u></b>			
	TO KNOCK AND STRAIGHTEN NECESSARY PORTION. INCLUSIVE OF THE REPAIR OF REAR END PANEL OUTER.		400.00	250.00
	TO CHECK ALL NECESSARY LIGHTINGS. }		60.00	40.00
	TO INSTALL PARKING SENSOR. }		80.00	-
	TO SPRAY PAINT THE AFFECTED AREAS.	NOT NECESSARY	300.00	-
	TO REMOVE UPHOLSTERY.	NOT NECESSARY	120.00	-
			960.00	290.00
	<b>GRAND TOTAL</b>		<b>1,786.57</b>	<b>661.32</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>661.32</b>

Report Ref No. CS/UOI22001387/Uqy3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.