

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

2/5/22 13800

Vehicle No: GBK3394L
 Chassis No: JTFHT02P700152160
 Engine No: 1KD2453788
 MAKE: TOYOTA
 MODEL: /TOYOTA HIACE VAN TURBO 5 DR MANUAL
 Replacement of Damaged Parts

Report No : SA1M222B0001_11-02-2022_175558
 Date : 15/2/2022
 TYPE : COMMERCIAL

sdarf
not Authorized
mm
marcus
MP 90096608
15/2/22
Zohar's Auto Repair

The Repairer of the following:
 • To resurvey before/after spray painting
 • To resurvey damaged part(s) during resurvey
 • Part prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No "right of refusal" is allowed
 • Supplemental work (item/s) must be resurveyed and approved by the Insurance Company
 Acknowledged by Repairer
 Signature:
 Description Qty Our Recommendation

S/No.

| S/No. | Description | Qty | Our Recommendation | |
|-------|--|-----|--------------------|-------------|
| 1 | Tailgate <i>1955.10 2nd hand</i> | 1 | | \$ 2,162.70 |
| 2 | Tailgate emblem <i>1568.10</i> | 1 | | \$ 371.85 |
| 3 | Rear bumper <i>To. 1</i> | 1 | | \$ 381.30 |
| 4 | Rear bumper bracket RH <i>one</i> | 1 | | \$ 151.45 |
| 5 | Rear bumper side retainer RH <i>one</i> | 1 | | \$ 182.45 |
| 6 | End panel outer <i>NP</i> | 1 | | \$ 371.75 |
| 7 | Tail lamp RH <i>366.10 5/20</i> | 1 | | \$ 381.90 |
| 8 | Tail lamp lower garnish RH <i>157.10 Dis</i> | 1 | | \$ 271.75 |
| 9 | Tail lamp lower garnish bracket RH <i>MS</i> | 1 | | \$ 174.45 |
| 10 | Tail lamp fender RH <i>R</i> | 1 | | \$ 1,712.45 |
| 11 | 1-set Reverse sensor <i>Shock</i> | 1 | | \$ 200.00 |
| | | | | \$ 6,362.05 |

Total (Parts): \$ 6,362.05

Labour Charges

- * To remove and transfer/reinstall the rear windscreen \$ 150.00 *100*
- * Rear windscreen sealant \$ *mm* 50.00 *40 s/w*
- * To dismantle and renew/refit/transfer the tail gate fittings, wiper motor to the new tail gate, re-set of same. \$ 150.00 *60*
- * To dismantle and renew the reverse sensor including re-set of same. \$ 80.00 *40*
- * To dismantle and replace of the accident damaged parts; to heat/weld, cut-off the end panel inner, end panel outer, fender, including knocking, repair, reshape and adjust of same. \$ 1,250.00 *900*
- * To putty and spray painting on tail gate inner and outer, rear bumper, tail lamp lower garnish, end panel outer, fender RH, including knocking, repair, reshape and adjust of same. \$ 1,200.00 *650*
- * To apply rustproofing on the repaired and replaced tailgate and fender RH. \$ 150.00 *60*
- * Sticker 70km/h \$ *all* 10.00 *s/w*

Total Labour: \$ 3,040.00

Subtotal \$ 9,402.05
 Gst 7% \$ 658.14

Total cost of repairs (Total cost of parts + Total Labour Cost): \$ 10,060.19

P. 3027.35
252
9,272.51
S.N. - 250
41810 47047
3824