



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22001388/Utf3e2	
			Date: 01/03/2022	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SGL 20X	Veh. Inspected	GBK 3394L
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2200544/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	14/02/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA HIACE (M)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	JTFHT02P700152160	Colour	WHITE
	Odometer	196961 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195/80 R15	DUNLOP	6 mm
	L/H Front Tyre	195/80 R15	DUNLOP	6 mm
	R/H Rear Tyre	195/80 R15	DUNLOP	6 mm
	L/H Rear Tyre	195/80 R15	DUNLOP	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	11/02/2022	Inspection Date	15/02/2022
	Survey held at	25 Senang Crescent		
	Repairer	ABWIN SERVICE PTE LTD		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	