



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SML 5700M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BOOT	TO REPAIR SEE LABOUR	1,259.00	-
1	REAR BUMPER	BUCKLED / WARPED	1,250.60	936.50
	LESS 20% DISCOUNT		-	-187.30
			2,509.60	749.20
	<b><u>LABOUR</u></b>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS,PANEL BEAT & RESHAPE THE AFFECTED AREA.INCLUSIVE OF THE REPAIR OF REAR BOOT.		1,800.00	400.00
	RESPRAY PAINT,PUTTY ON PARTS REPLACED & REPAIRED AREA.		1,600.00	400.00
	TO REMOVE & REFIX WIRING & CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREA FOR PROPER FUNCTIONS.		600.00	15.00
	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS.	NOT NECESSARY	150.00	-
			4,150.00	815.00
	<b>GRAND TOTAL</b>		<b>6,659.60</b>	<b>1,564.20</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,250.00</b>

Report Ref No. CS/SMR22001389/Kvf3n2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.