

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG22001395/BPA3Q2**Date:** 09/06/2022REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 7210026018   |
| <b>Claimant Vehicle No :</b> | SKG8500D                             | <b>Insured Vehicle No :</b> | GBF8327A     |
| Date of Loss:                | 29/01/2022                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 6346084702SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SKG8500D</b>                   | Engine No:  | 1ZZ3228230        |
| Make & Model:               | TOYOTA WISH, 1.8 (A)              | Chassis No: | JTDER12W703001907 |
| Reg. Date:                  | 03/04/2009 (Man. Year: 2009)      | Odometer:   | 383455 km         |
| Colour:                     | White                             |             |                   |
| Engine Capacity:            | 1794 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |                |                  |                |
|-------------------|----------------|------------------|----------------|
| Front Tyre Size:  | 195/65 R15     | Rear Tyre Size:  | 195/65 R15     |
| Front Left Side:  | West Lake 6 mm | Rear Left Side:  | West Lake 6 mm |
| Front Right Side: | West Lake 6 mm | Rear Right Side: | West Lake 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-------------------|-------------------|---------------|
| Parts   | 8,441.05          | 2,516.70          | 5,924.35          | 70.18         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour  | 3,550.00          | 1,260.00          | 2,290.00          | 64.51         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing  | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>11,991.05</b>  | <b>3,776.70</b>   | <b>8,214.35</b>   | <b>68.50</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>3,000.00</b>   |                   |               |
| <b>(S\$)</b>                                    | 11,991.05         | 3,000.00          | 8,991.05          | 74.98         |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 839.37            | 210.00            | 629.37            | 74.98         |
| <b>Nett Amount (S\$)</b>                        | <b>12,830.42</b>  | <b>3,210.00</b>   | <b>9,620.42</b>   | <b>74.98</b>  |
| <b>+ Loss of Use (8.0 x S\$80.00/day) (S\$)</b> |                   | 640.00            |                   |               |
| <b>(S\$)</b>                                    |                   | 3,850.00          |                   |               |
| <b>Liabile Amount (50.00%) (S\$)</b>            |                   | <b>1,925.00</b>   |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 7.45              |                   |               |
| <b>+ Other Costs (S\$)</b>                      |                   | 90.00             |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>2,022.45</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>              |                   | <b>2,000.00</b>   |                   |               |

INSPECTION

|                             |            |  |
|-----------------------------|------------|--|
| Date of Assignment:         | 14/02/2022 |  |
| Date Inspected:             | 14/02/2022 | Inspected At: 160 SIN MING DRIVE #01-14        |
| Estimated Period of Repair: | 6.0 days   | Repairer: Team Autopro Pte Ltd - Sin Ming (HQ) |

---

**Adjuster:** Lim Teow Guan

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                            | Condition     | Repairer's  | Amount     |
|-----|-----|----------|--|---------------|-------------|------------|
| 1   | 1   |          | *BONNET                                | Dented        | 680.00 FL   | *665.00 FL |
| 2   | 1   |          | *BONNET CHROME MOULDING                | Bent          | 198.00 FL   | *114.30 FL |
| 3   | 1   |          | *BONNET LOGO                           | Necessary     | 58.00 FL    | *58.00 FL  |
| 4   | 1   |          | *BONNET INNER LOCK                     | Not Damaged   | 90.80 FL    | *- FL      |
| 5   | 1   |          | *FRONT BUMPER                          | Broken        | 859.20 FL   | *499.90 FL |
| 6   | 1   |          | *FRONT BUMPER REINFORCEMENT            | Not Damaged   | 287.00 FL   | *- FL      |
| 7   | 1   |          | *FRONT BUMPER INNER SPONGE             | Broken        | 182.00 FL   | *78.80 FL  |
| 8   | 2   |          | *FRONT BUMPER FOG LAMP                 | No such part  | 416.00 FL   | *- FL      |
| 9   | 2   |          | *FRONT BUMPER FOG LAMP BRACKET         | No such part  | 300.00 FL   | *- FL      |
| 10  | 1   |          | *FRONT BUMPER GRILLE                   | Broken        | 198.40 FL   | *110.20 FL |
| 11  | 1   |          | *FRONT SUPPORT PANEL                   | Bent          | 732.80 FL   | *695.90 FL |
| 12  | 1   |          | *FRONT SUPPORT PANEL TOP GARNISH       | No such part  | 174.60 FL   | *- FL      |
| 13  | 1   |          | *FRONT SUPPORT CENTRE BRACKET          | No such part  | 65.20 FL    | *- FL      |
| 14  | 2   |          | *FRONT CHASSIS BRACKET                 | Not Damaged   | 331.80 FL   | *- FL      |
| 15  | 1   |          | *HEADLAMP                              | N/S Broken    | 1,680.00 FL | *786.30 FL |
| 16  | 2   |          | *HEADLAMP BRACKET                      | Not Damaged   | 442.80 FL   | *- FL      |
| 17  | 1   |          | *A/C CONDENSER                         | Not Damaged   | 1,280.00 FL | *- FL      |
| 18  | 1   |          | *A/C SUCTION PIPE                      | Not Damaged   | 210.00 FL   | *- FL      |
| 19  | 1   |          | *A/C DISCHARGE PIPE                    | Not Damaged   | 184.60 FL   | *- FL      |
| 20  | 1   |          | *RADIATOR                              | Not Damaged   | 1,180.60 FL | *- FL      |
| 21  | 1   |          | *RADIATOR FAN COWLING                  | Not Damaged   | 385.60 FL   | *- FL      |
| 22  | 1   |          | *SUNDRIES                              | Not Necessary | 80.00 FS    | *- FS      |
| 23  | 1   |          | *BONNET SEALANT                        | Necessary     | 100.00 FS   | *30.00 FS  |
| 24  | 1   |          | *BONNET CHROME MOULDING CLIPS          | No such part  | 50.00 FS    | *- FS      |
| 25  | 1   |          | *FRONT BUMPER CLIPS                    | Necessary     | 50.00 FS    | *30.00 FS  |
| 26  | 2   |          | *FRONT BUMPER SIDE RETAINER            | Necessary     | 268.00 FS   | *130.40 FS |
| 27  | 1   |          | *FRONT BUMPER GRILLE CLIPS             | Necessary     | 50.00 FS    | *30.00 FS  |
| 28  | 1   |          | *FRONT SUPPORT PANEL SEALANT           | Not Necessary | 100.00 FS   | *- FS      |
| 29  | 1   |          | *FRONT SUPPORT PANEL TOP GARNISH CLIPS | No such part  | 50.00 FS    | *- FS      |
| 30  | 1   |          | *A/C FLUID                             | Not Necessary | 80.00 FS    | *- FS      |
| 31  | 1   |          | *RADIATOR COOLANT                      | Not Necessary | 80.00 FS    | *- FS      |
| 32  | 1   |          | *FRONT NUMBER PLATE W/CASING           | Missing       | 80.00 FS    | *40.00 FS  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|  |                  |                 |
|--|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>10,925.40</b> | <b>3,268.80</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | 2,484.35         | 752.10          |
| <b>Total Parts (\$\$)</b>                                  | <b>8,441.05</b>  | <b>2,516.70</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                  | Particulars                | Lab.Type | Repairer's                    | Amount          |
|---------------------|----------------------------|----------|-------------------------------|-----------------|
| <b>Labour Items</b> |                            |          |                               |                 |
| 1                   | R&R FRONT BONNET COMPONENT | New      | 150.00                        | 60.00           |
| 2                   | R&R A/C CONDENSER          | New      | 150.00                        | 0.00            |
| 3                   | R&R RADIATOR               | New      | 150.00                        | 0.00            |
| 4                   | CHECK WIRING               | New      | 100.00                        | 0.00            |
| 5                   | UPHOLSTERY                 | New      | 200.00                        | 0.00            |
| 6                   | PANEL BEATING              | New      | 1,400.00                      | 800.00          |
| 7                   | RUST PROOFING              | New      | 200.00                        | 0.00            |
| 8                   | SPRAY PAINTING             | New      | 1,200.00                      | 400.00          |
|                     |                            |          | <b>Gross Labour Cost (\$)</b> | <b>3,550.00</b> |
|                     |                            |          |                               | <b>1,260.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >