



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 7674D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT LH TAILLAMP LOWER PANEL	CRACKED	1,450.00	1,450.00
1	FRONT LH HEADLAMP ASSY	CRACKED	1,520.00	1,520.00
1	FRONT LH TAILLAMP LOWER PANEL INNER STRUCTURE	BENT	1,030.00	1,030.00
1	FRONT CENTER PANEL	CRACKED	2,550.00	2,550.00
2	FRONT CENTER PANEL BRACKETS LH & RH UPPER @ \$610.00	NOT NECESSARY	1,220.00	-
1	FRONT RH TAILLAMP LOWER PANEL	CRACKED	1,450.00	1,450.00
1	FRONT CENTER PANEL BRACKETS LH LOWER	NOT NECESSARY	585.00	-
1	FRONT LH FOG LAMP (ADDITIONAL)	CRACKED	193.00	193.00
	LESS 10% DISCOUNT		-	-819.30
			9,998.00	7,373.70
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	ADVERTISEMENT WRAP (SN)	NECESSARY	1,600.00	800.00
			1,600.00	800.00
	<b><u>LABOUR</u></b>			
	CHECK WIRING.		30.00	30.00
	LABOUR CHARGES.		1,500.00	1,000.00
	SPRAY PAINTING.		1,000.00	800.00
			2,530.00	1,830.00
	<b>GRAND TOTAL</b>		<b>14,128.00</b>	<b>10,003.70</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>8,000.00</b>

Report Ref No. CS/AGI22001399/Rtf3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.