

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001403/RQY3Q2**Date:** 05/09/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00246722100		
Claimant Vehicle No :	SJD5756E	Insured Vehicle No :	SKL9193Z		
Date of Loss:	06/02/2022	Nature of Claim:	TP	Claim No:	SNM22D200880/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJD5756E		Engine No:	3SZ2062079
Make & Model:	TOYOTA RUSH, 1.5 X (A)		Chassis No:	J200E0020315
Reg. Date:	27/03/2008 (Man. Year: 2008)		Odometer:	198511 km
Colour:	White			
Engine Capacity:	1495 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R16	Rear Tyre Size:	215/65 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,260.75	3,702.70	1,558.05	29.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,840.00	1,280.00	560.00	30.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,100.75	4,982.70	2,118.05	29.83
+ GST 7.00/7.00% (S\$)	497.05	348.79	148.26	29.83
Nett Amount (S\$)	7,597.80	5,331.49	2,266.31	29.83

INSPECTION

Date of Assignment:	05/04/2022	
Date Inspected:	15/02/2022 Inspected At:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Sep 2022)
Parts: M1-SUV	TOYOTA RUSH 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJD5756E)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	841.90 FL	*841.90 FL
2	1		*TAILGATE RUSH LOGO	Necessary	92.70 FL	*69.50 FL
3	1		*TAILGATE RUBBER	Necessary	270.90 FL	*219.00 FL
4	1		*TAILGATE INNER LOCK	Not Necessary	217.60 FL	*- FL
5	1		*TAILGATE INNER TRIM BOARD	Not Necessary	489.70 FL	*- FL
6	1		*TAILGATE SPARE WHEEL COVER OUTER	Cracked	1,704.80 FL	*1,508.00 FL
7	1		*TAILGATE SPARE WHEEL COVER INNER	Cracked	583.70 FL	*583.70 FL
8	2		*TAILGATE SPARE WHEEL COVER LOCK LH & RH	Not Necessary	540.20 FL	*- FL
9	1		*REAR BUMPER	Deformed	880.80 FL	*880.80 FL
10	1		*REAR BUMPER SIDE RETAINER LH & RH	O/S Necessary	140.20 FL	*70.10 FL
11	1		*REAR BUMPER CLIPS (15 PCS)	Necessary	82.50 FL	*40.00 FL
12	1		*REAR BUMPER TOW COVER RH	Missing	45.10 FL	*45.10 FL
13	1		*REAR END PANEL	Not Necessary	317.80 FL	*- FL
14	1		*REAR END PANEL TOP GARNISH	Not Necessary	127.60 FL	*- FL
15	1		*NUMBER PLATE	Bent	35.00 FS	*35.00 FS
16	1		*SET REVERSE SENSOR	Not Working	200.00 FS	*200.00 FS
17	1		*INNER SEAL	Necessary	20.00 FS	*20.00 FS
18	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
19	1		*SPARE TYRE (NPA)	Not Necessary	0.00 FS	*- FS
20	1		*TAILGATE SPARE WHEEL HOLDER BRACKET	Bent	273.40 FL	*273.40 FL
21	1		*TAILGATE SPARE WHEEL HOLDER CLIP	Necessary	12.10 FL	*12.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,916.00	4,838.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,655.25	1,135.90
Total Parts (\$\$)	5,260.75	3,702.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	0.00
2	TO REMOVE AND REINSTALL REPLACE FRONT /REAR WINDSCREEN	New	120.00	120.00
3	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS	New	80.00	60.00
4	TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD END PANEL TO KNOCK & REPAIR FLOOR PANEL INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	800.00	500.00
5	TO SPRAY TAILGATE ,SPARE TYRE COVER ,REAR BUMPER ,END PANEL ,FLOOR PANEL	New	800.00	600.00
			Gross Labour Cost (\$)	1,840.00
				1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >