

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001406/EVY3N2**Date:** 04/03/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00002632101
Claimant Vehicle No :	SLG9228Y	Insured Vehicle No :	SLZ9903G
Date of Loss:	10/02/2022	Nature of Claim:	TP
		Claim No:	SNM22D201051/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG9228Y	Engine No:	L13A4160373
Make & Model:	HONDA FIT, 1.3 (A)	Chassis No:	GE61146451
Reg. Date:	16/09/2009 (Man. Year: 2008)	Odometer:	179165 km
Colour:	White		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55R15	Rear Tyre Size:	195/55R15
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,922.96	1,911.68	1,011.28	34.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	1,940.00	1,260.00	39.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,122.96	3,851.68	2,271.28	37.09
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	6,122.96	3,100.00	3,022.96	49.37
+ GST 7.00/7.00% (S\$)	428.61	217.00	211.61	49.37
Nett Amount (S\$)	6,551.57	3,317.00	3,234.57	49.37

INSPECTION

Date of Assignment:	14/02/2022	
Date Inspected:	15/02/2022	Inspected At: MOVA AUTOMOTIVE PTE LTD 15 FAN YONG ROAD SINGAPORE 629792
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2022)
Parts:	144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG9228Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	771.50 FL	*771.50 FL
2	1		*TAILGATE GLASS MOULDINGS	Necessary	74.00 FL	*74.00 FL
3	1		*TAILGATE EMBLEM-FIT	Necessary	35.00 FL	*35.00 FL
4	1		*TAILGATE LOCK	Bent	189.50 FL	*189.50 FL
5	1		*TAILGATE WEATHERSTRIP	Torn	92.30 FL	*92.30 FL
6	1		*TAILGATE INNER TRIM	Not Necessary	100.70 FL	*- FL
7	1		*TAILLAMP ASSY LH	Broken	206.80 FL	*206.80 FL
8	1		*REAR FENDER LH	Repair	652.40 FL	*- FL
9	1		*REAR END PANEL	Dented	765.50 FL	*356.00 FL
10	1		*REAR END PANEL TOP GARNISH	Crushed	62.80 FL	*62.80 FL
11	1		*REAR BUMPER	Dented	497.40 FL	*497.40 FL
12	1		*REAR BUMPER RETAINER LH	Broken	16.80 FL	*16.80 FL
13	10		*REAR BUMPER CLIPS	Necessary	31.20 FS	*30.00 FS
14	1		*REAR CHASSIS MEMBER LH (NPA)	Not Necessary	0.00 FS	*- FS
15	1		*SPARE WHEEL PANEL (NPA)	Not Necessary	0.00 FS	*- FS
16	1		*REAR FENDER INNER TRIM LH (NPA)	Not Necessary	0.00 FS	*- FS
17	1		*TAILGATE GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
18	1		*REAR QUATER GLASS SEALANT LH	Not Necessary	40.00 FS	*- FS
19	1		*REAR NUMBER PLATE	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,615.90	2,372.10
- List Item Discount on L Items 20.00/20.00% (S\$)	692.94	460.42
Total Parts (S\$)	2,922.96	1,911.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT/WELD REAR FENDER LH,REAR END PANEL,KNOCK AND STRAIGHTEN REAR CHASSIS MEMBER LH,SPARE WHEEL PANEL.REMOVE AND REPLACE ACCIDENT DAMAGED PARTS.REALIGN ALL CONNECTION	New	1,200.00	1,000.00
2	SPRAY PAINT TAILGATE,REAR FENDER LH,REAR CHASSIS MEMBER LH,SPARE WHEEL PANEL,REAR END PANEL,REAR BUMPER	New	1,000.00	800.00
3	REMOVE & REPLACE TAILGATE GLASS AND CHECK WATER LEAKAGE	New	120.00	50.00
4	REMOVE & REPLACE TAIL GATE INNER TRIM,MECHANISM AND CHECK LOCKING SYSTEM	New	60.00	30.00
5	REMOVE & REPLACE REAR QUATER GLASS AND CHECK WATER LEAKAGE	New	100.00	0.00
6	REMOVE & REPLACE REAR SEAT ASSY,REAR FENDER TRIM,COVERING,FLOOR CARPET,UPHOLSTERY	New	160.00	30.00
7	REMOVE & REPLACE PETROL TANK,HOSE,GARNISH	New	80.00	0.00
8	TO APPLY SEAL ON WELDING JOINTS	New	100.00	0.00
9	CHECK CHASSIS ALIGNMENT ON LASER LOCK MACHINE	New	280.00	0.00
10	RUST PROOF AFFECTED AREA	New	100.00	30.00
Gross Labour Cost (S\$)			3,200.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >