

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22001422/KQF3N2**Date:** 08/03/2022REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001372195

Claimant Vehicle No : SKL9097T**Insured Vehicle No :** SGM1611D

Date of Loss: 04/02/2022

Nature of Claim: TP Claim No: 269437

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKL9097T**

Make & Model: MERCEDES-BENZ CLA200, 1.6 (R18) (A)

Engine No: 27091030284404

Reg. Date: 06/01/2014 (Man. Year: 2013)

Chassis No: WDD1173432N046586

Colour: Metallic Grey

Odometer: 90409 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40R18

Rear Tyre Size: 225/40R18

Front Left Side: Continental 7 mm

Rear Left Side: Continental 7 mm

Front Right Side: Continental 7 mm

Rear Right Side: Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,672.53	5,123.02	3,549.51	40.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,570.00	1,850.00	1,720.00	48.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,242.53	6,973.02	5,269.51	43.04
Approved Total (Overridden) (S\$)		5,550.00		
(S\$)	12,242.53	5,550.00	6,692.53	54.67
+ GST 7.00/7.00% (S\$)	856.98	388.50	468.48	54.67
Nett Amount (S\$)	13,099.51	5,938.50	7,161.01	54.67

INSPECTION

Date of Assignment: 15/02/2022

Date Inspected: 15/02/2022 Inspected At:

Ready Auto Care Pte Ltd (HQ)
Blk 10 Ang Mo Kio Industrial Park 2A, #03-06,
AMK Auto Point
Singapore 568047

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Mar 2022)

Parts: 143 MERCEDES-BENZ CLA200 1.6 (R18) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKL9097T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LEFT DOOR	Bent	1,714.00 F	*1,714.00 FL
2	1		*REAR LEFT DOOR LOCK	Repair	315.65 F	*- FL
3	1		*REAR LEFT DOOR GLASS CHROME	Serviceable	200.09 F	*- FL
4	1		*REAR LEFT DOOR WEATHER STRIPS	Necessary	265.36 F	*265.36 FL
5	1		*REAR LEFT FENDER	Bent	2,889.00 F	*2,720.00 FL
6	1		*REAR LEFT OUTER PARKING SENSOR	Serviceable	202.23 F	*- FL
7	1		*REAR LEFT WHEEL HUP BEARING	Serviceable	354.17 F	*- FL
8	1		*REAR LEFT KNUCKLE ARM	Serviceable	1,425.24 F	*- FL
9	1		*REAR LEFT UPPER ARM	Serviceable	163.71 F	*- FL
10	1		*REAR LEFT LOWER ARM	Serviceable	154.08 F	*- FL
11	1		*RL SPORT RIM	Dented	954.00 F	*954.00 FN
12	1		*SET BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	8,672.53	5,688.36
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	469.94
- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00	95.40
Total Parts (\$\$)	8,672.53	5,123.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL DAMAGED PARTS,KNOCK OUT DENTS,JACK OUT DAMAGED PANEL,ADJUST,REPLACE,RESHAPE,CUT,WELD,REFIX & REALIGN BODY STRUCTURE	New	1,500.00	800.00
2	SPRAY PAINTING FOR NEW AND REPAIR PARTS INCLUDING SUPPLY OF PAINTS MATERIALS	New	1,200.00	750.00
3	REMOVE & REFIX RR UNDERCARRIAGE PARTS TO CHECK	New	260.00	0.00
4	COMPUTERISE 4 WHEELS ALIGNMENT	New	60.00	60.00
5	TO REMOVE & REFIX FLOOR & ROOF LINING,SEAT ETC TO FACILITATE REPAIR	New	250.00	100.00
6	COMPUTERISE REPROGRAMMING PARKING SENSOR & REAR LEFT DOOR FALSE MEMORY	New	150.00	60.00
7	CHECK WIRING,LIGHTING SYSTEM FOR PROPER FUNCTION	New	50.00	20.00
8	CAVITY PRESERVATION ON ALL AFFECTED AREAS	New	100.00	60.00
Gross Labour Cost (\$\$)			3,570.00	1,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >