

ASS. REC. BY:

REF: MSG/ 22001422/Kg


Kenneth

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s Ready
of _____
Insured: _____ 3ABD
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SKL 9097T Yr Regn: 01, 14
Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or A
Make: Mer CLA 200 c.c. 1595
Colour: M. Grey A/C: Insured / Std / NI / NA
Sp. Reading: 90409 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WDD1173432N 04 8586
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD / R/Rim or
Tyre Size: F: 225/40R18
R: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Continental
Front R/Bal: 7 mm
Rear R/Bal: 7 mm
L/Bal: 7 mm
L/Bal: 7 mm
D.O.A. 4/2/22 D.O.I. 15/2/2022
Survey held at ✓

Bal. or Market Value: \$ 48K
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: 07 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
N/S Rear body
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? : Prell. Report
 : Final Report

Days Of Repair: _____
Resurvey No. of Trip: _____

1) Date/Time, File Return to?

Survey Fee:
Transportation:
\$ - RS. SI
Fuel
Others
TOTAL

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech Invs (\$ _____)
 : Weekend (\$ _____)

Report Format :
Lump Sum / I.B.I: (\$ _____)

Ready Auto Care Pte Ltd - We Care For All Your Car Needs

Blk 10 # 03-06 AMK Auto Point, Ang Mo Kio Ind Park 2A, Ang Mo Kio Ave 5. Singapore 568047
 Tel : 64810304 Fax : 64815587 Reg No : 200600989K GST No : 200600989k

MSIG

Motorcar Claim Department
 Attn Claim Officer

*NOT Authorized
 L1 Rep @
 Recovery After Paint*

Estimate Repair

Date : 14/02/2022

Accident Involving SKL9097T & SGM1611D On 04/02/2022 At Open Carpark

SKL9097T

Mercedes CLA200

Item	Descriptions	Amount
1	Rear Left Door	\$ 1,714.00 ✓
2	Rear Left Door Lock	\$ 315.65 X
3	Rear Left Door Glass Chrome	\$ 200.09 X
4	Rear Left Door Weather Strips	\$ 265.36 ✓
5	Rear Left Fender	\$ 2,889.00 ✓
6	Rear Left Outer Parking Sensor	\$ 202.23 ?
7	Rear Left Wheel Hup Bearing	\$ 354.17 ?
8	Rear Left Knuckle Arm	\$ 1,425.24 ?
9	Rear Left Upper Arm	\$ 163.71 X
10	Rear Left Lower Arm	\$ 154.08 X
Total For Parts (Less 10%)		\$ 7,683.53

S/N Item (s)	Amount
1 RL Sport Rim	\$ 954.00 ✓
2 Bumper Clips - 1 Set	\$ 35.00 ✓
Total For S/N	\$ 989.00

Labour & Misc	Amount
1 To Remove All Damaged Parts, Knock Out Dents, Jack Out Damaged Panel Panel, Adjust, Replace, Reshape, Cut, Weld, Refix & Realign Body Structure	\$ 1,500.00 800l
2 Spray Painting For New And Repair Parts Including Supply Of Paints Materials	\$ 1,200.00 750l
3 Remove & Refix RR Undercarriage Parts To Check	\$ 260.00 ?
4 Computerise 4 Wheels Alignment	\$ 60.00 ✓
5 To Remove & Refix Floor & Roof Rining, Seat etc To Facilitate Repair	\$ 250.00 100l
6 Computerise Reprogramming Parking Sensor & Rear Left Door False Memory	\$ 150.00 60l
7 Check Wiring, Lighting System For Proper Function	\$ 50.00 20l
8 Cavity Preservation On All Affected Areas	\$ 100.00 60l
Total For Labour & Misc	\$ 3,570.00

Total For Parts & Labour \$ 12,242.53

Ready Auto Care Pte Ltd

Sulynn - 96606551

No Of Days For Repair 8 Days

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: