



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 8537E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
10	BUMPER CLIP	NECESSARY	12.00	12.00
1	COVER-RR BUMPER	DENTED	468.60	468.60
1	GARNISH ASSY-GUSSET,LH	NOT NECESSARY	94.80	-
1	GARNISH ASSY-GUSSET,RH	NOT NECESSARY	95.30	-
1	BRACKET-RR BUMPER SIDE MTG,RH	NOT NECESSARY	19.20	-
1	BRACKET ASSY-RR BUMPER SIDE MTG	NOT NECESSARY	19.50	-
1	BRACKET-RR BUMPER SIDE MTG,RH	NOT NECESSARY	19.50	-
1	BRACKET-RR BUMPER SIDE LWR,LH	NOT NECESSARY	19.50	-
1	STEP PLATE-RR BUMPER	BROKEN	57.90	57.90
1	ABSORBER-REAR BUMPER ENERGY	NOT NECESSARY	74.30	-
1	RAIL ASSY-REAR BUMPER	NOT NECESSARY	347.00	-
1	BRACKET-STEP MTG,LH	NOT NECESSARY	6.20	-
1	BRACKET-STEP MTG,RH	NOT NECESSARY	6.20	-
1	PANEL ASSY-TAIL GATE	DENTED	2,620.40	2,620.40
1	LATCH ASSY-TAIL GATE	NOT NECESSARY	84.00	-
1	BELL CRANK ASSY-TAIL GATE	NOT NECESSARY	152.40	-
1	LINK ASSY-TAIL GATE INSIDE	NOT NECESSARY	38.20	-
1	HANDLE ASSY-TAIL GATE	NOT NECESSARY	25.40	-
1	LIFTER ASSY-TAIL GATE,LH	NOT NECESSARY	93.40	-
1	LIFTER ASSY-TAIL GATE,RH	NOT NECESSARY	93.40	-
1	EMBLEM-HYUNDAI	NECESSARY	30.20	30.20
1	EMBLEM-H-1	NECESSARY	26.30	26.30
1	SYMBOL MARK-H	NECESSARY	26.20	26.20
1	GARNISH-T/GATE	NOT NECESSARY	53.60	-
1	SEALING PAD-GARNISH	NOT NECESSARY	24.30	-
1	LAMP ASSY-LICENSE PLATE,LH	NOT NECESSARY	25.90	-
1	LAMP ASSY-LICENSE PLATE,RH	NOT NECESSARY	25.90	-
1	GLASS ASSY-T/GATE	NOT NECESSARY	432.90	-
1	LAMP ASSY-RR COMBINATION LH	NOT NECESSARY	384.90	-
1	LAMP ASSY-RR COMBINATION RH	NOT NECESSARY	384.90	-

Report Ref No. CS/SMR22001424/Eqf3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-1,152.46	-648.32
			4,609.84	2,593.28
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	TAILGATE SEALANT (SN)	NECESSARY	100.00	100.00
1	REAR GLASS SEALANT (SN)	NECESSARY	108.00	108.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	40.00	-
			248.00	208.00
	<b><u>LABOUR</u></b>			
	TO TRANSFER TAIL GATE MECHANISM.		380.00	380.00
	TO SUPPLY R&I REAR GLASS TO FACILITATE REPAIR.		180.00	180.00
	TO CARRY OUT ACCIDENT BODY REPAIR.		2,660.00	760.00
	COMPLETE PUTTY AND SPRAY PAINT ALL AFFECTED AREAS.		1,700.00	340.00
	TO SUPPLY & INSTALL TINTED SOLAR FILM.	NOT NECESSARY	340.00	-
			5,260.00	1,660.00
	<b>GRAND TOTAL</b>		<b>10,117.84</b>	<b>4,461.28</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>4,461.28</b>

Report Ref No. CS/SMR22001424/Eqf3n2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.