

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC22001426/Vqf3e2
	300 BEACH ROAD SINGAPORE 1995	#17-04/07 THE CONCOURSE 55		Date:	10/03/2022
				Code:	LPC2
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	XD 8270D	Veh. Inspected		SLC 657Y
	Policy No.		Coverage (\$)		0.00
	Claim No.	21/22/22/VC00/025405	Excess (\$)		0.00
	Assign From	GERALD POH	Assign Date		15/02/2022
2. Vehicle Particulars & Condition					
	Make & Model	MITSUBISHI LANCER 2.0L	c.c		1998
	Engine No.	HIDDEN	Year of Reg.		2008
	Chassis No.	JMYSTCY4A8U000733	Colour		GREY
	Odometer	249200 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	205/60 R16	YOKOHAMA		5 mm
	L/H Front Tyre	205/60 R16	YOKOHAMA		5 mm
	R/H Rear Tyre	205/60 R16	YOKOHAMA		5 mm
	L/H Rear Tyre	205/60 R16	YOKOHAMA		5 mm
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE O/S BODY.			
5.	General Information				
	Accident Date	24/01/2022	Inspect Date /	Time	15/02/2022 (02:00 PM)
	Survey held at	MHL AUTOMOBILE SERVICES			
		BLK 3006, UBI ROAD 1 #01-360 SINGAPORE 408700			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC22001426/Vqf3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser