



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 3529L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LAMP ASSY,TURN SIGNAL,FR LH (SN)	BROKEN	288.20	288.20
1	HEADLAMP ASSY,LH (SN)	NOT NECESSARY	679.23	-
1	PANEL ASSY,CAB,FR (SN)	DENTED	2,560.15	2,560.15
1	GRILLE,RADIATOR (SN)	NOT NECESSARY	1,038.02	-
1	BRACKET,RADIATOR GRILLE,CTR (SN)	NOT NECESSARY	37.64	-
1	PANEL,CAB FR CORNER,LH (SN)	NOT NECESSARY	722.63	-
1	BUMPER,FR (SN)	DENTED	1,355.04	1,355.04
1	COVER,FR BUMPER,LH (SN)	CUT	484.95	484.95
1	STAY,FR BUMPER,LH (SN)	NOT NECESSARY	278.53	-
1	MARK,FUSO (SN)	NECESSARY	219.98	219.98
1	MARK,THREE-DIA (SN)	NOT NECESSARY	117.83	-
1	MARK,CANTER (SN)	NOT NECESSARY	112.02	-
1	STEP,FR SIDE,LH (SN)	CUT	409.05	409.05
			8,303.27	5,317.37
	<u>LABOUR</u>			
	TO REMOVE AND REFIX DAMAGED PARTS,CUT,WELD,PANEL BEAT,STRAIGHTEN & REALIGN,ETC.		3,000.00	1,800.00
	TO CHECK FOR AND RECTIFY WIRING FAULTS,TO CONDUCT DIAGNOSTICS CHECK.		180.00	30.00
	TO PUTTY,CLEAN,SPRAY PAINT AND POLISH,ETC.		1,750.00	1,050.00
	TO REMOVE AND REFIX FRONT DASHBOARD.		700.00	600.00
			5,630.00	3,480.00
	GRAND TOTAL		13,933.27	8,797.37
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)			8,797.37

Report Ref No. CS/INC22001428/Evf3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.