

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	NTUC INCOME IN	SURANCE CO-OPERATIVE LTD		Ref:	CS/INC22001428/Evf3e2	
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE		Date:	09/05/2022	
	ATTN: SERENE LI	M		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBJ 2081B	Veh. Inspected		YQ 3529L	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1161458-001	Excess (\$)		0.00	
	Assign From	ANNIE KOH	Assign Date		15/02/2022	
2. Vehicle Particulars & Condition						
	Make & Model	MITSUBISHI CANTER	c.c		2998	
	Engine No.	HIDDEN	Year of Reg.		2021	
	Chassis No.	FEB21EA35357	Colour		WHITE	
	Odometer	37878 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/85 R15	DUNLOP		4 mm	
	L/H Front Tyre	195/85 R15	DUNLOP		4 mm	
	R/H Rear Tyre	195/85 R15	DUNLOP		4 mm	
	L/H Rear Tyre	195/85 R15	DUNLOP		4 mm	
4.	1. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
	DAMAGES SEE DETAILS.					
		. .			5.0	
5.	. General Information					
	Accident Date	05/02/2022	Inspect Date / T	ime	15/02/2022 (10:34 AM)	
	Survey held at	GOLDBELL ENGINEERING PTE	LTD			
	,	10 TUAS AVE 18 SINGAPORE 638894				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.					
5b.	B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. Estimate Days of Repair					
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				
					37	