



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 9986P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (SN)	BROKEN	1,787.00	1,787.00
1	FRONT BUMPER FIXING PARTS (SN)	NOT NECESSARY	612.00	-
2	FRONT BUMPER SECURING STRIP (SN)	NOT NECESSARY	79.00	-
1	FRONT BUMPER CLOSING ELEMENT-LOWER CENTER (SN)	NOT NECESSARY	254.00	-
1	FRONT BUMPER AIR GUIDE-RH (SN)	NOT NECESSARY	72.00	-
1	FRONT BUMPER AIR GUIDE GRILLE-RH (SN)	NOT NECESSARY	409.00	-
1	FRONT PARKING AID SENSOR-INNER/OUTER (SN)	NOT NECESSARY	244.00	-
4	FRONT PARKING AID SENSOR SEAL RING (SN)	NOT NECESSARY	10.00	-
1	FRONT BUMPER GUIDE SECTION-RH (SN)	BROKEN	41.00	40.30
1	FRONT FENDER-RH (SN)	DENTED	861.00	861.00
1	FRONT FENDER ATTACHMENT PARTS (SN)	NOT NECESSARY	211.00	-
1	FRONT FENDER CLOSING ELEMENT-RH (SN)	BROKEN	81.00	80.30
1	FRONT FENDER BRACKET-RH (SN)	NOT NECESSARY	41.00	-
6	POP RIVET (SN)	NECESSARY	23.00	22.80
1	FRONT FENDER BRACE-RH (SN)	BENT	132.00	131.50
1	FRONT FENDER BRACKET CENTER-RH (SN)	NOT NECESSARY	55.00	-
1	FRONT WHEEL HOUSING LINER-RH (SN)	CRUSHED	262.00	262.00
1	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS (SN)	NOT NECESSARY	219.00	-
1	FRONT WHEEL SPOILER (SN)	NOT NECESSARY	82.00	-
1	FRONT FENDER END PLATE-RH (SN)	NOT NECESSARY	40.00	-
1	FRONT FENDER STONE CHIP GUARD-RH (SN)	NOT NECESSARY	57.00	-
1	HEADLIGHT-RH (SN)	NOT NECESSARY	7,693.00	-
1	LIFT CYLINDER-RH (SN)	NOT NECESSARY	231.00	-
1	LIFT CYLINDER CORRUGATED PIPE (SN)	NOT NECESSARY	107.00	-
1	FRONT FENDER LEDGE COVER LONG-RH (SN)	NOT NECESSARY	35.00	-
1	FRONT FENDER LEDGE COVER SHORT-RH (SN)	NOT NECESSARY	26.00	-
1	RHS FRONT RIM (SN)	TO REPAIR SEE LABOUR	1,278.00	-
1	SUNDRIES (SN)	NOT NECESSARY	350.00	-
			15,292.00	3,184.90

Report Ref No. CS/INC22001429/Eqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID.		480.00	480.00
	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	NOT NECESSARY	350.00	-
	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER AND RHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.INCLUSIVE OF THE REPAIR OF RHS FRONT RIM.		2,100.00	1,400.00
	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.		2,000.00	1,500.00
	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.		280.00	280.00
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00
			5,402.00	3,852.00
	GRAND TOTAL		20,694.00	7,036.90
RECOMMENDED COST OF REPAIRS (CONFIRMED)				7,036.90

Report Ref No. CS/INC22001429/Eqf3n2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.