

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22001434/Bqy3e2
	8 SHENTON WAY SINGAPORE 0688		Date:	16/03/2022	
				Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 1298R	Veh. Inspected	k	SDQ 1515M
	Policy No.	VFX/P2419138	Coverage (\$)		0.00
	Claim No.	S2M03TC6	Excess (\$)		0.00
	Assign From	KOH JANICE	Assign Date		15/02/2022
2.	Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ S320L	c.c		2996
	Engine No.	HIDDEN	Year of Reg.		2018
	Chassis No.	WDD2221622A447748	Colour		GREY
	Odometer	52263 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	245/45 R19	MICHELIN		5 mm
	L/H Front Tyre	245/45 R19	MICHELIN		5 mm
	R/H Rear Tyre	275/40 R19	MICHELIN		5 mm
	L/H Rear Tyre	275/40 R19	MICHELIN		5 mm
4.	Description of Damages				
	THE VEHICLE SUS	E VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.			
5.	. General Information				
	Accident Date	13/02/2022	Inspect Date /	Time	15/02/2022 (03:49 PM)
	Survey held at EM SOLUTION PTE LTD				
	160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM22001434/Bqy3e2

Inspected By

J. Mm

LIM TEOW GUAN

Automotive Assessor

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser