

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. MBL 9859

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT MUDGUAL (CONSISTENT)	BROKEN	78.00	78.00
1	FRONT NO PLATE (CONSISTENT)	NECESSARY	30.00	30.00
1	BRAKE LEVER R (CONSISTENT)	CUT	28.00	28.00
2	MIRRLE R/L (CONSISTENT)	O/S CUT	58.00	29.00
1	HANDLE BAR (CONSISTENT)	BENT	98.00	98.00
2	BELESEN R/L (CONSISTENT)	MISSING	48.00	35.00
1	HANDLE GRIP (CONSISTENT)	TORN	38.00	30.00
1	HEAD LIGHT (CONSISTENT)	CUT	185.00	185.00
1	HEAD COWLING (CONSISTENT)	CUT	78.00	78.00
2	R/L FRONT FORK COVER (CONSISTENT)	O/S BROKEN	76.00	30.00
2	R/L FRONT SIDE FAILING (CONSISTENT)	CUT	170.00	170.00
1	BRAKE PEDAL (CONSISTENT)	BENT	78.00	78.00
1	ASSY FRONT FOOT LEST BAR (CONSISTENT)	BENT	95.00	95.00
1	EXHAUST PIPE FULLSTEM (CONSISTENT)	DENTED	295.00	295.00
2	R/L BEAR FOOT BRACKET (CONSISTENT)	BROKEN	150.00	150.00
2	REAR FOOT REST R/L (CONSISTENT)	CUT	48.00	40.00
2	R/L REAR SIDE COVER (CONSISTENT)	CUT	180.00	150.00
1	REAR KATONG ASSY (RH ABSORBER) (CONSISTENT)	BENT	180.00	150.00
1	REAR SEAT BAR (CONSISTENT)	CUT	78.00	78.00
	LESS 10% DISCOUNT		-	-182.70
			1,991.00	1,644.30
	<u>LABOUR</u>			
	TOWING .		45.00	45.00
	FRONT FORK REPAIR.		150.00	100.00
	LABOUR.		180.00	150.00
			375.00	295.00
	GRAND TOTAL		2,366.00	1,939.30

Report Ref No. CC4/ASM22001437/Epa3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,550.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC4/ASM22001437/Epa3q2



Automotive Assessor

mont

HO LEONG CHUAN

**Automotive Assessor**