

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001439/BVY3Q2**Date:** 04/03/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNA00223952101

Claimant Vehicle No : SJE8558K**Insured Vehicle No :** SLH2416L

Date of Loss: 10/02/2022

Nature of Claim: TP

Claim No: SNM22D201040/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJE8558K**

Make & Model: MERCEDES-BENZ E250, 1.8 (A)

Engine No: 27492030196482

Reg. Date: 01/08/2014 (Man. Year: 2014)

Chassis No: WDD2120362B036836

Colour: Silver

Odometer: 29568 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	265/35 R18
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	Pirelli 4 mm	Rear Right Side:	Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,519.13	9,828.69	11,690.44	54.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,650.00	1,760.00	2,890.00	62.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,169.13	11,588.69	14,580.44	55.72
Approved Total (Overridden) (S\$)		9,250.00		
(S\$)	26,169.13	9,250.00	16,919.13	64.65
+ GST 7.00/7.00% (S\$)	1,831.84	647.50	1,184.34	64.65
Nett Amount (S\$)	28,000.97	9,897.50	18,103.47	64.65

INSPECTION

Date of Assignment: 15/02/2022

Date Inspected: 15/02/2022 Inspected At:

160 SIN MING DR #01-14 SIN MING AUTO CITY
SINGAPORE 575722

Repairer: Team Autopro Pte Ltd (Sin Ming)

Estimated Period of Repair: 6.0 days

Adjuster: Lim Teow Guan**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Mar 2022)
Parts:	143	MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJE8558K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	2,487.90 FL	*- FL
2	1		*BOOTLID LOGO	Necessary	110.00 FL	*40.00 FL
3	1		*BOOTLID EMBLEM E250	Necessary	84.00 FL	*66.70 FL
4	1		*BOOTLID EMBLEM CYCLE & CARRIAGE	Necessary	89.00 FL	*76.00 FL
5	1		*BOOTLID EMBLEM 7G TRONIC	Necessary	88.00 FL	*65.00 FL
6	1		*BOOTLID WEATHER STRIP	Not Damaged	468.00 FL	*- FL
7	1		*BOOTLID INNER LOCK ASSY	Jammed	274.00 FL	*274.00 FL
8	2		*BOOTLID LAMP	Not Damaged	1,365.80 FL	*- FL
9	1		*REAR BUMPER	Broken	2,086.00 FL	*1,510.00 FL
10	1		*REAR BUMPER LOWER	Broken	786.30 FL	*340.00 FL
11	1		*REAR BUMPER LOWER CHROME MOULDING	No such part	275.30 FL	*- FL
12	1		*REAR BUMPER REINFORCEMENT	Bent	698.00 FL	*698.00 FL
13	1		*REAR BUMPER LOWER COVER	No such part	336.50 FL	*- FL
14	1		*REAR BUMPER LOWER BEAM GARNISH	No such part	113.90 FL	*- FL
15	3		*REAR BUMPER BRACKET	Necessary	435.00 FL	*270.00 FL
16	2		*REAR BUMPER SIDE RETAINER	Necessary	112.00 FL	*112.00 FL
17	1		*REAR BUMPER REVERSE SENSOR (6 PCS)	Scratched (2 PCS ONLY)	1,590.00 FL	*200.00 FL
18	1		*REAR BUMPER HEAT SHIELD	Not Damaged	288.00 FL	*- FL
19	1		*REAR BUMPER TOW CAP	Not Damaged	125.00 FL	*- FL
20	1		*REAR END PANEL OUTER	Dented	1,125.00 FL	*1,125.00 FL
21	1		*REAR END PANEL INNER	Not Damaged	995.00 FL	*- FL
22	1		*REAR END PANEL TOP GARNISH	Broken	215.00 FL	*215.00 FL
23	2		*TAILLAMP	Broken	1,460.00 FL	*1,370.00 FL
24	2		*TAILLAMP OUTER GARNISH	Not Damaged	360.00 FL	*- FL
25	2		*TAILLAMP BRACKET	Not Damaged	178.00 FL	*- FL
26	2		*FRONT HEADREST	Activated	2,880.00 FL	*2,880.00 FL
27	1		*AIRBAG CONTROL MODULE	Activated	1,899.00 FL	*1,011.25 FL
28	2		*AIRBAG SENSOR	Activated	649.40 FL	*397.60 FL
29	2		*REAR EXHAUST PIPE CHROME TIP	Not Damaged	690.00 FL	*- FL
30	1		*REAR EXHAUST PIPE HEAT SHIELD	Not Damaged	181.60 FL	*- FL
31	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
32	1		*BOOTLID SEALANT	Not Necessary	100.00 FS	*- FS
33	2		*BOOTLID LAMP SEAL	Not Necessary	120.00 FS	*- FS
34	2		*BOOTLID LAMP CLIPS	Not Necessary	120.00 FS	*- FS
35	1		*REAR BUMPER CLIPS	No	50.00 FS	*30.00 FS
36	1		*REAR BUMPER LOWER CLIPS	Necessary	50.00 FS	*30.00 FS
37	6		*REAR BUMPER REVERSE SENSOR SEAL	Necessary	348.00 FS	*43.20 FS
38	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
39	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
40	2		*TAILLAMP CLIPS	No such part	100.00 FS	*- FS
41	2		*TAILLAMP SEAL	Necessary	120.00 FS	*40.00 FS
42	1		*REAR NUMBER PLATE W/CASING	Bent	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **23,763.70** **10,893.75**
- List Item Discount on L Items 10.00/10.00% (\$\$) 2,244.57 1,065.06

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (\$\$)	21,519.13 9,828.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R BOOTLID COMPONENT	New	150.00	0.00
2	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
3	R&R FRONT HEADREST	New	300.00	180.00
4	DIAGNOSTIC RESET FAULT CODE	New	300.00	120.00
5	CHECK WIRING	New	100.00	0.00
6	UPHOLSTERY	New	300.00	0.00
7	PANEL BEATING	New	1,600.00	800.00
8	RUST PROOFING	New	200.00	0.00
9	SPRAY PAINTING	New	1,600.00	600.00
Gross Labour Cost (S\$)			4,650.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >