

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001440/ATY3S2**Date:** 25/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00144362101

Claimant Vehicle No : GBG923B **Insured Vehicle No :** YP9678E

Date of Loss: 14/02/2022 Nature of Claim: TP Claim No: SNM22D201062/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG923B**

Make & Model: NISSAN NV200, 1.5 (M) Engine No: K9KC400D056519

Reg. Date: 31/05/2017 (Man. Year: 2016) Chassis No: VSKYBAM20Z0141642

Colour: Grey Odometer: 148475 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14C Rear Tyre Size: 175/70 R14C

Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,115.59	11,327.64	2,787.95	19.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,520.00	3,030.00	1,490.00	32.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,635.59	14,357.64	4,277.95	22.96
Approved Total (Overridden) (S\$)		11,400.00		
(S\$)	18,635.59	11,400.00	7,235.59	38.83
+ GST 7.00/7.00% (S\$)	1,304.49	798.00	506.49	38.83
Nett Amount (S\$)	19,940.08	12,198.00	7,742.08	38.83

INSPECTION

Date of Assignment: 15/02/2022

Date Inspected: 15/02/2022 Inspected At: N-51 Automotive Pte Ltd (kaki Bukit Autohub) (HQ)
KAKI BUKIT AUTOHUB 2 KAKI BVUKIT AVE 2
#01-18
Singapore 417921

Estimated Period of Repair: 11.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 25 May 2022)	
Parts:	N/A	NISSAN NV200 1.5 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG923B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ENGINE INTERCOOLER HOSE	Cut	236.00 FL	*236.00 FL
2	2		*FRONT AIR GUIDE GARNISH (BOTTOM) L/R	Not Necessary	90.00 FL	*- FL
3	2		*FRONT AIR GUIDE GARNISH (TOP) L/R	Deformed	75.40 FL	*75.40 FL
4	1		*FRONT BUMPER	Deformed	655.20 FL	*655.20 FL
5	1		*FRONT BUMPER INNER SPONGE	Cracked	326.50 FL	*326.50 FL
6	1		*FRONT BUMPER REINFORCEMENT	Bent	625.90 FL	*625.90 FL
7	2		*FRONT BUMPER SIDE RETAINER L/R	Not Necessary	50.00 FL	*- FL
8	1		*FRONT BUMPER TOW HOOK COVER	Not Necessary	21.00 FL	*- FL
9	1		*FRONT GRILLE	Cracked	356.20 FL	*356.20 FL
10	1		*FRONT GRILLE LOGO EMBLEM	Necessary	64.90 FL	*64.90 FL
11	1		*FRONT GRILLE LOWER MOULDING	Not Necessary	85.00 FL	*- FL
12	2		*FRONT HEADLAMP L/R	Cracked	979.80 FL	*979.80 FL
13	2		*FRONT HEADLAMP LOWER GARNISH L/R	Torn	640.00 FL	*640.00 FL
14	1		*FRONT TOP PANEL	Not Necessary	251.40 FL	*- FL
15	1		*REAR BUMPER	Deformed	485.90 FL	*485.90 FL
16	1		*REAR BUMPER LH REFLECTOR	Not Necessary	61.90 FL	*- FL
17	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	74.40 FL	*- FL
18	1		*REAR BUMPER SPONGE	Cracked	94.00 FL	*94.00 FL
19	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	15.00 FL	*- FL
20	1		*REAR END PANEL (INNER)	Dented	697.00 FL	*697.00 FL
21	1		*REAR END PANEL TOP GARNISH	Deformed	83.90 FL	*83.90 FL
22	1		*REAR LH TAILGATE	Distorted	1,469.60 FL	*1,469.60 FL
23	1		*REAR LH TAILGATE LOGO EMBLEM	Necessary	64.90 FL	*64.90 FL
24	1		*REAR LH TAILGATE NV200 EMBLEM	Necessary	136.00 FL	*136.00 FL
25	1		*REAR LH TAILGATE DEAR LINK	Not Necessary	90.00 FL	*- FL
26	2		*REAR LH TAILGATE HINGES	Not Necessary	214.40 FL	*- FL
27	1		*REAR LH TAILGATE MECHANISM LOCK (LOWER)	Damaged	115.90 FL	*115.90 FL
28	1		*REAR LH TAILGATE MECHANISM LOCK (TOP)	Not Necessary	108.90 FL	*- FL
29	1		*REAR LH TAILGATE TRIM COVER	Deformed	213.00 FL	*213.00 FL
30	1		*REAR LH TAILGATE WIPER MOTOR	Damaged	305.80 FL	*305.80 FL
31	1		*REAR LH TAILLAMP	Cracked	277.20 FL	*277.20 FL
32	1		*REAR RH TAILGATE	Dented	1,102.20 FL	*1,102.20 FL
33	1		*REAR RH TAILGATE MECHANISM LOCK (LOWER)	Not Necessary	115.90 FL	*- FL
34	1		*REAR RH TAILGATE TRIM COVER	Not Necessary	200.00 FL	*- FL
35	1		*REAR RH TAILGATE WEATHER (VERTICAL)	Not Necessary	72.60 FL	*- FL
36	1		*REAR TAILGATE CENTER LOCK MECHANISM	Damaged	253.80 FL	*253.80 FL
37	1		*REAR TAILGATE WEATHER STRIP	Cut	88.90 FL	*88.90 FL
38	1		*ENGINE INTERCOOLER	Dented	2,121.60 FL	*2,121.60 FL
39	1		*REAR TAILGATE REVERSE CAMERA	Damaged	1,012.50 FS	*450.00 FS
40	1		*FLOOR TOP PANEL TRIM COVER	Not Necessary	400.00 FS	*- FS
41	2		*SET FRONT AIR GUIDE GARNISH CLIPS L/R	Necessary	60.00 FS	*20.00 FS
42	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
43	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FS	*20.00 FS
44	1		*FRONT NUMBER PLATE	Dented	35.00 FS	*35.00 FS
45	1		*FRONT NUMBER PLATE HOLDER	Deformed	50.00 FS	*30.00 FS
46	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
48	1		*REAR END PANEL (OUTER)	Dented	150.00 FS	*- FS
49	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	40.00 FS	*10.00 FS
50	1		*REAR LH TAILGATE 70KM STICKER	Necessary	25.00 FS	*10.00 FS
51	1		*REAR LH TAILGATE NUMBER PLATE	Not Necessary	35.00 FS	*- FS
52	1		*REAR LH TAILGATE NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
53	1		*SET REAR LH TAILGATE OUTER GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
54	1		*REAR LH TAILGATE WINDSCREEN SEAL	Necessary	50.00 FS	*40.00 FS
55	1		*REAR LH TAILGATE WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
56	1		*REAR RH TAILGATE WINDSCREEN SEAL	Necessary	50.00 FS	*40.00 FS
57	1		*REAR RH TAILGATE WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	15,407.60	12,474.60
- List Item Discount on L Items 10.00/10.00% (S\$)	1,292.01	1,146.96
Total Parts (S\$)	14,115.59	11,327.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTNG HEADLAMP FOCUSNG AND REWIRE FOR PARKING SENSOR.	New	80.00	30.00
2	TO REMOVE TAILGATE GLASS.	New	280.00	120.00
3	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)	New	120.00	80.00
4	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.	New	1,800.00	1,200.00
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	New	2,000.00	1,400.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	New	100.00	80.00
7	TO REMOVE, REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION.	New	140.00	120.00
Gross Labour Cost (\$\$)			4,520.00	3,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >