

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22001442/TQY3E2**Date:** 17/10/2022**REFERENCE**

Insured/Claimant:	NG CHIANG WEI	Policy No:	1800016337-04	
Date of Loss:	12/02/2022	Nature of Claim:	OD	Claim No: 4662869527SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJC6537U		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK049179
Reg. Date:	01/02/2018 (Man. Year: 2017)	Chassis No:	WAUZZZF41JA062799
Colour:	Grey	Odometer:	65117 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$106,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,360.00	6,482.48	14,877.52	69.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,122.00	2,772.00	2,350.00	45.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,482.00	9,254.48	17,227.52	65.05
- Excess (S\$)	550.00	550.00	0.00	0.00
(S\$)	25,932.00	8,704.48	17,227.52	66.43
+ GST 7.00/7.00% (S\$)	1,815.24	609.31	1,205.93	66.43
Nett Amount (S\$)	27,747.24	9,313.79	18,433.45	66.43

INSPECTION

Date of Assignment:	15/02/2022	
Date Inspected:	15/02/2022	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,787.00 FS	*1,429.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	2,111.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTER	Not Necessary	219.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTER	Not Necessary	254.00 FS	*- FS
6	2		*FRONT BUMPER AIR GUIDE-LH/RH	Not Necessary	144.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,478.00 FS	*1,182.40 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Not Necessary	151.00 FS	*- FS
9	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	139.00 FS	*110.80 FS
10	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	899.00 FS	*719.20 FS
11	2		*FRONT BUMPER GUIDE SECTION-LH/RH	Not Necessary	82.00 FS	*- FS
12	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
13	1		*CAUTION STICKER	Not Necessary	16.00 FS	*- FS
14	1		*AIR COND STICKER	Not Necessary	9.00 FS	*- FS
15	1		*FRONT BUMPER LOCK CARRIER BRACKET	Bent	154.00 FS	*122.80 FS
16	2		*FRONT BUMPER SUPPORT-LH/RH	Not Necessary	64.00 FS	*- FS
17	4		*POP RIVET	Necessary	4.00 FS	*2.88 FS
18	1		*HORN-LH	Not Necessary	134.00 FS	*- FS
19	1		*HORN SUPPORT-LH	Not Necessary	33.00 FS	*- FS
20	1		*FRONT PARKING AID SENSOR-INNER/OUTER	Not Necessary	244.00 FS	*- FS
21	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
22	1		*BONNET	Bent	3,425.00 FS	*2,740.00 FS
23	1		*BONNET ATTACHMENT PARTS	Not Necessary	431.00 FS	*- FS
24	3		*BONNET IMPACT PROTECTION-CENTER/LH/RH	Necessary	93.00 FS	*73.20 FS
25	1		*BONNET STRIKER-LH	Not Necessary	56.00 FS	*- FS
26	1		*BONNET LOCK	Not Necessary	228.00 FS	*- FS
27	1		*BONNET BOWDEN CABLE	Not Necessary	64.00 FS	*- FS
28	1		*BONNET RELEASE LEVER	Not Necessary	15.00 FS	*- FS
29	1		*BONNET BOWDEN CABLE-CENTER	Not Necessary	64.00 FS	*- FS
30	1		*BONNET RELEASE CABLE COVER	Not Necessary	11.00 FS	*- FS
31	1		*FRONT WHEEL HOUSING LINER-LH	Not Necessary	260.00 FS	*- FS
32	1		*FRONT WHEEL SPOILER	Not Necessary	82.00 FS	*- FS
33	1		*HEADLIGHT-LH	Not Necessary	7,693.00 FS	*- FS
34	1		*LIFT CYLINDER-LH	Not Necessary	231.00 FS	*- FS
35	1		*LIFT CYLINDER CORRUGATE PIPE	Not Necessary	107.00 FS	*- FS
36	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Distorted	21.00 FS	*16.32 FS
37	1		*RADIATOR AIR GUIDE OUTER-LH	Not Necessary	32.00 FS	*- FS
38	1		*RADIATOR AIR GUIDE INNER-LH	Deformed	14.00 FS	*10.88 FS
39	1		*RADIATOR AIR GUIDE UPPER	Not Necessary	19.00 FS	*- FS
40	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
41	1		*SUNDRIES	Necessary	300.00 FS	*14.40 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **21,360.00** **6,482.48**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND RHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,122.00	2,772.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >