



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 4090Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	N/S HEADLAMP	CRACKED	2,816.50	2,816.50
2	N/S HEADLAMP CLIP @\$5.00	NECESSARY	10.00	10.00
1	FRONT BUMPER	BADLY DENTED	481.25	481.25
1	FRONT BUMPER SIDE RETAINER N/S	BENT	131.40	131.40
8	FRONT BUMPER CLIP @\$8.00	NECESSARY	64.00	30.00
1	FRONT N/S FENDER "VTI" EMBLEM	NOT NECESSARY	53.50	-
1	FRONT N/S FENDER	TO REPAIR SEE LABOUR	581.45	-
	LESS 25% DISCOUNT		-	-867.29
			4,138.10	2,601.86
	<u>LABOUR</u>			
	REMOVE THE NECESSARY AFFECTED PARTS,STRAIGHTEN FRONT N/S FENDER AND BONNET,N/S HEADLAMP PANEL AND REPLACE PARTS.INCLUSIVE OF THE REPAIR OF FRONT N/S FENDER .		1,200.00	300.00
	PUTTY AND SPRAYPAINT ON ALL AFFECTED PARTS.		900.00	400.00
	CHECK ELECTRICAL.		20.00	20.00
	TUFF KOTE.		50.00	30.00
	REWIRE FRONT PORTION AND REFOCUS N/S HEADLAMP BEAM.		50.00	30.00
			2,220.00	780.00
	GRAND TOTAL		6,358.10	3,381.86
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,700.00

Report Ref No. CS3/GRB22000619/Evf3e2-1

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.