

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22001448/UPA3Q2**Date:** 02/11/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SMH9786K **Insured Vehicle No :** SMN2983Y

Date of Loss: 09/02/2022 Nature of Claim: TP Claim No: MFL2022D0000929

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH9786K**
 Make & Model: HONDA CIVIC, 1.6 (A) Engine No: R16B25502746
 Reg. Date: 19/02/2019 (Man. Year: 2018) Chassis No: MRHFC5650JT002332
 Colour: Silver Odometer: 30802 km
 Engine Capacity: 1597 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R16 Rear Tyre Size: 215/55 R16
 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
 Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,956.90	11,142.50	1,814.40	14.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,750.00	5,190.00	1,560.00	23.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,706.90	16,332.50	3,374.40	17.12
+ GST 7.00/7.00% (S\$)	1,379.48	1,143.28	236.20	17.12
Nett Amount (S\$)	21,086.38	17,475.78	3,610.60	17.12
+ Loss of Use (20.0 x S\$50.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		18,483.23		

INSPECTION

Date of Assignment: 15/02/2022

Date Inspected: 15/02/2022 Inspected At:

SME Motor Pte Ltd (Kaki Bukit)
1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 18.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 May 2022)
Parts:	143	HONDA CIVIC 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH9786K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BONNET (WCP)	Bent / Buckled	350.00 F	*350.00 F
2	2		*REAR BONNET HINGE (WCP)	Bent / Twisted	280.00 F	*280.00 F
3	1		*REAR BOOT LOCK (WCP)	Bent	75.00 F	*75.00 F
4	1		*REAR BOOT OUTER GARNISH (WCP)	Cracked	105.00 F	*105.00 F
5	1		*REAR BOOT CENTER LOGO (WCP)	Necessary	25.00 F	*25.00 F
6	1		*REAR BOOT CIVIC EMBLEM (WCP)	Necessary	30.00 F	*30.00 F
7	1		*REAR BOOT I-VTEC EMBLEM (WCP)	Necessary	30.00 F	*25.00 F
8	2		*REAR BOOT LAMP (WCP)	Cracked	240.00 F	*240.00 F
9	2		*REAR TAIL LAMP (WCP)	Cracked	390.00 F	*390.00 F
10	1		*REAR BUMPER (WCP)	Distorted	260.00 F	*260.00 F
11	2		*REAR BUMPER RETAINER (WCP)	Bent	30.00 F	*30.00 F
12	10		*REAR BUMPER CLIP (WCP)	Necessary	20.00 F	*20.00 F
13	2		*REAR BUMPER SIDE TRIM (WCP)	Cut	36.00 F	*36.00 F
14	1		*REAR BUMPER LOWER SPOILER (WCP)	Missing	50.00 F	*50.00 F
15	1		*REAR BUMPER REINFORCEMENT (WCP)	Bent	150.00 F	*150.00 F
16	1		*REAR BOOT INNER RUBBER (WCP)	Twisted	55.00 F	*55.00 F
17	1		*REAR END PANEL (WCP)	Badly Dented	260.00 F	*260.00 F
18	2		*REVERSE SENSOR (WCP)	Shorted	190.00 F	*190.00 F
19	1		*REAR END PANEL TOP GARNISH (WCP)	Twisted	45.00 F	*45.00 F
20	6		*REAR END PANEL TOP GARNISH CLIP (WCP)	Not Necessary	18.00 F	*- F
21	1		*REAR TAIL LAMP PANEL (WCP)	N/S Dented / O/S Repair	130.00 F	*65.00 F
22	1		*REAR SPARE TYRE FLOOR PANEL (WCP)	Buckled	480.00 F	*480.00 F
23	1		*REAR SPARE TYRE BOARD COVER (WCP)	Torn	80.00 F	*80.00 F
24	1		*REAR LH CHASSIS (NO STOCK) (WCP)	Repair	550.00 F	*- F
25	1		*REAR LH FENDER (WCP)	Bent / Buckled	620.00 F	*620.00 F
26	1		*REAR WINDSCREEN MOULDING (WCP)	Necessary	120.00 F	*120.00 F
27	1		*REAR LH FENDER GLASS MOULDING (WCP)	Not Necessary	145.00 F	*- F
28	4		*REAR PETROL TANK COVER RIVERT (WCP)	Necessary	20.00 F	*20.00 F
29	1		*FRT BONNET (WCP)	Buckled	430.00 F	*430.00 F
30	2		*FRT BONNET HINGE (WCP)	Bent	110.00 F	*110.00 F
31	1		*FRT BONNET LOCK (WCP)	Twisted	95.00 F	*95.00 F
32	1		*FRT GRILLE (WCP)	Cracked	90.00 F	*90.00 F
33	1		*FRT GRILLE OUTER MOULDING (WCP)	Cracked	105.00 F	*105.00 F
34	1		*FRT GRILLE CENTER LOGO (WCP)	Cracked	25.00 F	*25.00 F
35	4		*FRT GRILLE CLIP (WCP)	Necessary	8.00 F	*8.00 F
36	1		*FRT BUMPER (WCP)	Dented	260.00 F	*260.00 F
37	2		*FRT BUMPER RETAINER (WCP)	Bent	36.00 F	*36.00 F
38	10		*FRT BUMPER CLIP (WCP)	Necessary	20.00 F	*20.00 F
39	1		*FRT BUMPER TOP RUBBER SEAL (WCP)	Twisted	35.00 F	*35.00 F
40	1		*FRT BUMPER LOWER GRILLE (WCP)	Cut	50.00 F	*50.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*FRT BUMPER BEAM (BELLOW HEADLAMP) (WCP)	N/S Bent / O/S Not Necessary	50.00 F	*25.00 F
42	1		*FRT BUMPER REINFORCEMENT (WCP)	Dented	295.00 F	*295.00 F
43	2		*HEADLAMP (NO STOCK) (WCP)	Cracked	1,900.00 F	*1,900.00 F
44	1		*HEADLAMP SUPPORT PANEL (WCP)	Buckled / Twisted	450.00 F	*450.00 F
45	1		*HEADLAMP SUPPORT TOP GARNISH (WCP)	Not Necessary	40.00 F	*- F
46	8		*SUPPORT TOP GARNISH CLIP (WCP)	Not Necessary	16.00 F	*- F
47	1		*AIRCON CONDENSER (WCP)	Bent / Punctured	450.00 F	*450.00 F
48	1		*RADIATOR (WCP)	Punctured	460.00 F	*460.00 F
49	1		*RADIATOR MOTOR (WCP)	Jammed	260.00 F	*260.00 F
50	1		*RADIATOR MOTOR COWLING (WCP)	Cracked	85.00 F	*85.00 F
51	1		*RADIATOR FAN BLADE (WCP)	Bent	55.00 F	*55.00 F
52	1		*FRT BUMPER CENTER TOP BEAM (WCP)	Cracked	125.00 F	*125.00 F
53	2		*AIRCON SIDE DEFLECTOR (WCP)	Not Necessary	110.00 F	*- F
54	1		*FRT BUMPER FOG LAMP GARNISH (WCP)	N/S Grazed / O/S Not Necessary	90.00 F	*45.00 F
55	1		*HEADLAMP CHROME (WCP)	N/S Cracked / O/S Not Necessary	190.00 F	*95.00 F
56	2		*FRT FENDER (WCP)	Repair	440.00 F	*- F
57	2		*WIPER CORNER GARNISH (WCP)	Not Necessary	50.00 F	*- F
58	1		*REAR NUMBER PLATE	Bent	40.00 FS	*40.00 FS
59	1		*REAR WINDSCREEN GUM	Necessary	60.00 FS	*40.00 FS
60	1		*REAR LH FENDER GLASS GUM	Necessary	50.00 FS	*30.00 FS
61	1		*FRT NUMBER PLATE	Bent	40.00 FS	*40.00 FS
62	1		*RADIATOR COOLANT	Necessary	25.00 FS	*25.00 FS
63	1		*REAR FLOOR PANEL SEALANT	Necessary	60.00 FS	*50.00 FS
64	1		*AIR CLEANER BOX LOWER	Cracked	95.00 F	*95.00 F
65	1		*AMBIENCE SENSOR BRACKET	Damaged	10.00 F	*10.00 F
66	2		*REAR FLOOR PANEL SIDE JOINT	Buckled	150.00 F	*150.00 F
67	2		*REAR END PANEL SIDE JOINT	Bent	90.00 F	*90.00 F
68	1		*REAR ALARM BUZZER	Cracked	70.00 F	*70.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	11,804.00	10,150.00
+ Margin on L,N Items 10.00/10.00% (S\$)	1,152.90	992.50
Total Parts (S\$)	12,956.90	11,142.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	30.00
2	REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
3	REMOVE & REFIX REAR LH FENDER GLASS	New	60.00	60.00
4	REMOVE & REFIX CUSHION AND SEATS	New	180.00	100.00
5	REMOVE & REFIX PETROL TANK	New	180.00	60.00
6	REMOVE & REFIX REAR UNDERCARRIAGE (WITH CROSSMEMBER)	New	350.00	0.00
7	4 WHEEL ALIGNMENT	New	80.00	0.00
8	REMOVE & REFIX CUSHION AND SEATS	New	100.00	0.00
9	LABOUR CHARGE	New	3,000.00	2,800.00
10	SPRAY PAINTING	New	2,400.00	1,900.00
11	REMOVE & REFIX EXHAUST	New	250.00	120.00
Gross Labour Cost (\$\$)			6,750.00	5,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >