

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE		Ref:	CS3/ASM22001452/Tqy3e2		
	8 SHENTON WAY SINGAPORE 0688		Date:	24/02/2022		
	ATTN: OH VALE			Code:	ASM	
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SJP 5144H	Veh. Inspected	b	SMG 5151Z	
	Policy No.	VPA/P1235289	Coverage (\$)		0.00	
	Claim No.	S2M03S0P	Excess (\$)		0.00	
	Assign From	OH VALE	Assign Date		15/02/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	KIA CERATO	c.c		1591	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	KNAF3416MK5013756	Colour		BLACK	
	Odometer	74952 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/45 R17	BRIDGESTONE		6 mm	
	L/H Front Tyre	225/45 R17	BRIDGESTONE		6 mm	
	R/H Rear Tyre	225/45 R17	BRIDGESTONE		6 mm	
	L/H Rear Tyre	225/45 R17	BRIDGESTONE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUS UNDERCARRIAGE	VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION AND DERCARRIAGE.				
5.	. General Information					
	Accident Date	25/01/2022	Inspect Date /	Time	15/02/2022 ( 04:45 PM )	
	Survey held at EXCLUSIVE ENTERPRISE PTE LTD  8 KAKI BUKIT AVENUE 4 #03-49 PREMIER @ KAKI BUKIT SINGAPORE 415875					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days					

Report Ref No. CS3/ASM22001452/Tqy3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

M.MATAI, AMSAE-A
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.