

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22001455/APA3Q2**Date:** 08/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070054674
Claimant Vehicle No :	SLP357U	Insured Vehicle No :	SMT357L
Date of Loss:	26/01/2022	Nature of Claim:	TP
		Claim No:	2763958648SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP357U	Engine No:	B14XER19NG4135
Make & Model:	OPEL ADAM, 1.4 (A)	Chassis No:	W0L0MAP08G6117887
Reg. Date:	24/05/2017 (Man. Year: 2016)	Odometer:	68782 km
Colour:	Maroon		
Engine Capacity:	1398 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R16	Rear Tyre Size:	195/55 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,080.70	1,544.10	5,536.60	78.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,680.00	1,240.00	3,440.00	73.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,760.70	2,784.10	8,976.60	76.33
+ GST 7.00/7.00% (S\$)	823.25	194.89	628.36	76.33
Nett Amount (S\$)	12,583.95	2,978.99	9,604.96	76.33
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
Nett Liability (S\$)		3,158.99		

INSPECTION

Date of Assignment:	11/02/2022	
Date Inspected:	11/02/2022	Inspected At: 1st Autoworks Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01 Singapore 415933
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER UPPER	Deformed	1,415.00 FL	*1,415.00 FL
2	1		*REAR BUMPER LOWER EXTENSION	Not Necessary	952.00 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	522.00 FL	*- FL
4	1		*REAR BUMPER GUIDE LH-INNER	Not Necessary	62.00 FL	*- FL
5	1		*REAR BUMPER GUIDE RH-INNER	Not Necessary	62.00 FL	*- FL
6	1		*REAR BUMPER GUIDE LH-OUTER	Not Necessary	55.00 FL	*- FL
7	1		*REAR BUMPER GUIDE RH-OUTER	Not Necessary	55.00 FL	*- FL
8	1		*REAR BUMPER GUIDE CENTER	Not Necessary	73.00 FL	*- FL
9	1		*REAR BUMPER TOW COVER	Not Necessary	43.00 FL	*- FL
10	1		*REAR TAILGATE	Not Necessary	1,738.00 FL	*- FL
11	1		*REAR TAIL LAMP LH	Not Necessary	523.00 FL	*- FL
12	1		*REAR TAIL LAMP RH	Not Necessary	523.00 FL	*- FL
13	1		*REAR FOG LAMP	Cracked	234.00 FL	*234.00 FL
14	1		*REAR REVERSE LAMP	Not Necessary	230.00 FL	*- FL
15	1		*INSERT RR BUMPER ,RH	Not Necessary	106.00 FL	*- FL
16	1		*INSERT RR BUMPER ,LH	Not Necessary	106.00 FL	*- FL
17	1		*MOULDING ,CHROME ,RR BPR ,RH	Not Necessary	110.00 FL	*- FL
18	1		*MOULDING ,CHROME ,RR BPR ,LH	Not Necessary	110.00 FL	*- FL
19	1		*REAR END PANEL	Not Necessary	534.00 FL	*- FL
20	1		*REAR END PANEL TRIM	Not Necessary	180.00 FL	*- FL
21	1		*EMBLEM OPEL	Not Necessary	90.00 FL	*- FL
22	1		*SEALANT	Not Necessary	50.00 FS	*- FS
23	1		*REAR NUMBER PLATE	Cracked	40.00 FS	*35.00 FS
24	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,853.00	1,709.00
- List Item Discount on L Items 10.00/10.00% (\$)	772.30	164.90
Total Parts (\$)	7,080.70	1,544.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	2,500.00	650.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA (REAR TAILGATE ,REAR BUMPER ,REAR END PANEL)	New	1,800.00	550.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	60.00	0.00
4	REMOVE AND REFIT REVERSE SENSOR (LABOUR)	New	50.00	40.00
5	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE	New	150.00	0.00
6	TO REMOVE AND REFIX REAR TAIL GATE WINDSCREEN	New	120.00	0.00
Gross Labour Cost (\$\$)			4,680.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >