

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001456/TQY3N2**Date:** 09/06/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00125692100

**Claimant Vehicle
No :** GBD3536G**Insured
Vehicle No :** GBL5436G

Date of Loss: 28/01/2022

Nature of Claim: TP

Claim
No: SNM22D200991/C02/LEEPG**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **GBD3536G**Make & Model: MITSUBISHI CANTER, 3.0 D FEA01BR2SDEB (CBU)
(M)

Engine No: 4P10B30314

Reg. Date: 17/09/2014 (Man. Year: 2014)

Chassis No: FEA01BA00456

Colour: White

Odometer: 179293 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/R15

Rear Tyre Size: 195/R15(D)

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6/6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,594.12	16,664.12	6,930.00	29.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,040.00	3,330.00	1,710.00	33.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,634.12	19,994.12	8,640.00	30.17
Approved Total (Overridden) (S\$)		16,000.00		
(S\$)	28,634.12	16,000.00	12,634.12	44.12
+ GST 7.00/7.00% (S\$)	2,004.39	1,120.00	884.39	44.12
Nett Amount (S\$)	30,638.51	17,120.00	13,518.51	44.12

INSPECTION

Date of Assignment: 15/02/2022

Date Inspected: 16/02/2022 Inspected At:

 BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR
 C #01-68
 SINGAPORE 575643
 REPAIRER: EM-1 AUTO PTE LTD

Estimated Period of Repair: 10.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 09 Jun 2022)	
Parts:	N/A	mitsubishi canter 3.0 D FEA01BR2SDEB (CBU) (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD3536G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN	Cracked	1,131.40 FL	*1,131.40 FL
2	1		*FRONT WINDSCREEN RUBBER	Necessary	492.10 FL	*492.10 FL
3	1		*REAR NUMBER PLATE LAMP	Cracked	92.00 FL	*92.00 FL
4	1		*REAR NUMBER PLATE BRACKET	Missing	125.00 FL	*125.00 FL
5	2		*TAILLAMP ASSY	Cracked	586.00 FL	*586.00 FL
6	2		*TAILLAMP ASSY BASE	Bent	304.00 FL	*304.00 FL
7	1		*CENTRE EXHAUST PIPE	Bent	529.00 FL	*529.00 FL
8	1		*CENTRE EXHAUST MOUNTING	Bent	48.00 FL	*48.00 FL
9	1		*CENTRE EXHAUST BRACKET	Bent	65.00 FL	*65.00 FL
10	1		*CENTRE EXHAUST GASKED	Necessary	45.00 FL	*45.00 FL
11	1		*REAR EXHAUST SILENCER	Bent	695.00 FL	*695.00 FL
12	1		*REAR EXHAUST SILENCER MOUNTING	Bent	48.00 FL	*48.00 FL
13	2		*REAR EXHAUST BRACKET	Bent	130.00 FL	*130.00 FL
14	1		*REAR EXHAUST GASKED	Necessary	45.00 FL	*45.00 FL
15	1		*REAR MUDGUARD RH	Torn	250.00 FL	*250.00 FL
16	2		*TAILGATE DOOR ASSY FIBER	Cracked	4,000.00 FS	*3,000.00 FS
17	3		*TAILGATE DOOR HINGES (STAINLESS) LH	Bent	540.00 FS	*360.00 FS
18	1		*SET TAILGATE DOOR JOINT HINGE (STAINLESS) RH	Bent	450.00 FS	*300.00 FS
19	1		*TAILGATE DOOR TOP HINGE (STAINLESS) RH	Bent	180.00 FS	*180.00 FS
20	2		*TAILGATE DOOR OPENER BAR (STAINLESS)	Bent	1,000.00 FS	*600.00 FS
21	2		*TAILGATE DOOR OPENER BAR CATCH	Bent	300.00 FS	*300.00 FS
22	2		*TAILGATE DOOR OUTER HANDLE (STAINLESS)	Bent	900.00 FS	*700.00 FS
23	2		*TAILGATE DOOR STICKER WITH COMPANY LOGO	Necessary	1,000.00 FS	*600.00 FS
24	2		*TAILGATE DOOR SAFE LOCK	Bent	240.00 FS	*240.00 FS
25	1		*REAR FLOOR PANEL TOP ALUMINIUM PLATE	Bent	1,200.00 FS	*900.00 FS
26	2		*REAR PROTECTOR BIG STOPPER	Cut	300.00 FS	*200.00 FS
27	1		*REAR BUMPER	Missing	1,000.00 FS	*800.00 FS
28	2		*REAR BUMPER BRACKET	Missing	500.00 FS	*360.00 FS
29	1		*REAR REFRIGERATOR SIDE FIBER PANEL RH	Cracked	1,800.00 FS	*1,400.00 FS
30	1		*REAR REFRIGERATOR SIDE FIBER PANEL STICKER W/COMPANY LOGO RH	Necessary	800.00 FS	*600.00 FS
31	1		*REAR NUMBER PLATE	Missing	50.00 FS	*30.00 FS
32	1		*70KM STICKER	Necessary	15.00 FS	*15.00 FS
33	1		*SET REAR REFRIGERATOR SURROUND FRAME (STAINLESS)	Bent	5,800.00 FS	*2,600.00 FS
34	1		*SET REAR REFRIGERATOR SURROUND FRAME RIVET	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	24,740.50	17,810.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,146.38	1,146.38
Total Parts (\$\$)	23,594.12	16,664.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,500.00	1,600.00
2	SPRAY PAINTING	New	1,500.00	1,000.00
3	CHECK WIRING	New	40.00	30.00
4	TO JACK AND KNOCK ALIGN REAR CHASSIS FRAME LH	New	700.00	500.00
5	TO REMOVE AND INSTALL FRONT WINDSCREEN	New	120.00	100.00
6	TO REMOVE & INSTALL EXHAUST PIPE	New	180.00	100.00
Gross Labour Cost (\$)			5,040.00	3,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >