

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EG122001458/DVF3E2

Date: 25/07/2022

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : SNB5198D **Insured Vehicle No :** YP5396U
Date of Loss: 14/02/2022 Nature of Claim: TP Claim No: CDMCG22000300

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNB5198D**
Make & Model: HONDA FREED, 1.5 (A) Engine No: LEB7259682
Reg. Date: 26/08/2021 (Man. Year: 2021) Chassis No: GB73149734
Colour: Silver Odometer: 32402 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm
Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	39,519.20	4,914.92	34,604.28	87.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,100.00	1,100.00	5,000.00	81.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	45,619.20	6,014.92	39,604.28	86.81
Approved Total (Overridden) (S\$)		4,800.00		
(S\$)	45,619.20	4,800.00	40,819.20	89.48
+ GST 7.00/7.00% (S\$)	3,193.34	336.00	2,857.34	89.48
Nett Amount (S\$)	48,812.54	5,136.00	43,676.54	89.48

INSPECTION

Date of Assignment: 15/02/2022
Date Inspected: 15/02/2022 Inspected At: JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
AutoPoint
Singapore 568047
Estimated Period of Repair: 3.0 days

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jul 2022)
Parts:	M1-MPV	HONDA FREED 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNB5198D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	2,689.00 FL	*- FL
2	2		*BONNET HINGE LH / RH	Not Necessary	164.80 FL	*- FL
3	1		*BONNET LOCK	Not Necessary	298.00 FL	*- FL
4	1		*BONNET INSULATOR	Not Necessary	498.00 FL	*- FL
5	1		*BONNET SEAL	Not Necessary	128.00 FL	*- FL
6	2		*HEAD LAMP LH / RH	Cracked	8,248.00 FL	*4,276.40 FL
7	1		*HEAD LAMP LOWER BRACKET LH / RH	Not Necessary	636.00 FL	*- FL
8	1		*HEAD LAMP CONTROL MODULE LH / RH	Not Necessary	8,436.80 FL	*- FL
9	1		*HEAD LAMP WIREHARNES COMPLETE	Not Necessary	2,551.20 FL	*- FL
10	1		*FRONT GRILLE BASE	Mtg Cracked	1,489.20 FL	*740.00 FL
11	1		*FRONT GRILLE CHROME	Cracked	588.00 FL	*168.00 FL
12	1		*FRONT GRILLE LOGO	Cut	119.00 FL	*78.00 FL
13	1		*FRONT BUMPER	Mtg Cracked	1,424.50 FL	*837.50 FL
14	2		*FRONT BUMPER SIDE RETAINER LH / RH	Not Necessary	218.00 FL	*- FL
15	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	524.50 FL	*- FL
16	1		*FRONT BUMPER LOWER GARNISH	Not Necessary	419.00 FL	*- FL
17	2		*FRONT BUMPER LOWER SIDE GARNISH LH / RH	Not Necessary	788.00 FL	*- FL
18	1		*FRONT BUMPER TOW HOOK COVER	Not Necessary	89.00 FL	*- FL
19	1		*FRONT BUMPER UNDER COVER	Not Necessary	356.90 FL	*- FL
20	1		*FRONT BUMPER SPONGE	Not Necessary	401.00 FL	*- FL
21	1		*FRONT REINFORCEMENT BAR	Not Necessary	1,074.00 FL	*- FL
22	1		*FRONT SUPPORT PANEL	Not Necessary	2,157.20 FL	*- FL
23	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	349.80 FL	*- FL
24	2		*FRONT SUPPORT PANEL SIDE GARNISH LH / RH	Not Necessary	474.40 FL	*- FL
25	1		*FRONT BRACE PANEL	Not Necessary	259.80 FL	*- FL
26	1		*A/C CONDENSOR	Not Necessary	1,987.50 FL	*- FL
27	1		*A/C CONDENSOR DISCHARGE HOSE	Not Necessary	897.20 FL	*- FL
28	1		*A/C CONDENSOR SUCTION HOSE	Not Necessary	482.50 FL	*- FL
29	1		*RADIATOR ASSY	Not Necessary	2,398.50 FL	*- FL
30	1		*RADIATOR TOP HOSE	Not Necessary	89.00 FL	*- FL
31	1		*RADIATOR BOTTOM HOSE	Not Necessary	82.00 FL	*- FL
32	1		*RADIATOR FAN MOTOR	Not Necessary	419.00 FL	*- FL
33	1		*RADIATOR FAN BLADE	Not Necessary	254.00 FL	*- FL
34	1		*RADIATOR FAN COWLING	Not Necessary	524.00 FL	*- FL
35	1		*FRONT FENDER LH / RH	Not Necessary	2,588.00 FL	*- FL
36	2		*FRONT FENDER INNER SHIELD LH / RH	Not Necessary	756.00 FL	*- FL
37	2		*FRONT FENDER HYBRID EMBLEM LH / RH	Not Necessary	228.00 FL	*- FL
38	1		*FRONT RADAR ASSY	Not Necessary	2,581.90 FL	*- FL
39	1		*FRONT RADAR BRACKET	Not Necessary	941.80 FL	*- FL
40	1		*BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
41	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
42	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*15.00 FS
43	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
44	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
45	1		*FRONT BUMPER UNDER COVER CLIPS	Not Necessary	50.00 FS	*- FS
46	1		*FRONT FENDER INNER PANEL SEALANT	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
48	1		*COOLANT	Not Necessary	100.00 FS	*- FS
49	1		*FRONT NO. PLATE & GARNISH	Not Necessary	100.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					49,241.50	6,134.90
- List Item Discount on L Items 20.00/20.00% (\$\$)					9,722.30	1,219.98
Total Parts (\$\$)					39,519.20	4,914.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	250.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	600.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	450.00
4	TO TUFF COAT DAMAGED AREAS	New	150.00	20.00
5	TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	New	200.00	0.00
6	TO RNR RADIATOR & REFILL COOLANT TO FACILITATE REPAIRS	New	200.00	0.00
7	TO CALIBRATE FRONT RADAR ASSY	New	800.00	0.00
8	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
9	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$\$)			6,100.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >