



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: PAY DANIEL			Ref: CS3/ASM22001465/Tqy3e2 Date: 04/03/2022 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	CB 6286G	Veh. Inspected	FBR 9245H
	Policy No.	CN125708	Coverage (\$)	0.00
	Claim No.	S2M03S43	Excess (\$)	0.00
	Assign From	PAY DANIEL	Assign Date	14/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA NMAX	c.c	155
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	MH3SG5680LK052687	Colour	BLUE
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	110/70 R13	MAXXIS	5 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	130/70 R13	MAXXIS	5 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.			
5. General Information				
	Accident Date	25/01/2022	Inspection Date	26/02/2022
	Survey held at	5 Soon Lee Street #04-15 Pioneer Point		
	Repairer	JVS MOTORS		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	