

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunoss Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS22001466/KQF3N2**Date:** 05/04/2022**REFERENCE**

Insured/Claimant:	Ng Siok Hoon	Policy No:	MPC21P00174500	
Date of Loss:	10/02/2020	Nature of Claim:	OD	Claim No: DMPC2200063H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGK8671U		
Make & Model:	TOYOTA WISH, 1.8 (A)	Engine No:	1ZZ2654988
Reg. Date:	28/08/2006 (Man. Year: 2006)	Chassis No:	ZNE100319065
Colour:	Metallic Pearl White	Odometer:	93034 km
Engine Capacity:	1794 cc		
Market Value/New Car Price:	S\$31,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,071.90	3,041.50	4,030.40	56.99
Miscellaneous Items	3,160.00	1,085.00	2,075.00	65.66
Labour	3,160.00	1,740.00	1,420.00	44.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,391.90	5,866.50	7,525.40	56.19
Approved Total (Overridden) (S\$)		4,250.00		
(S\$)	13,391.90	4,250.00	9,141.90	68.26
+ GST 7.00/7.00% (S\$)	937.43	297.50	639.93	68.26
Nett Amount (S\$)	14,329.33	4,547.50	9,781.83	68.26

INSPECTION

Date of Assignment:	15/02/2022 Present Location:	Accord Auto Services Pte Ltd (HQ) Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point Singapore 568047
Date Inspected:	16/02/2022 Inspected At:	
Estimated Period of Repair:	10.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Apr 2022)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGK8671U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP LH (WCP)	Cracked	320.00 F	*320.00 F
2	1		*FRONT HEADLAMP LOWER BRACKET (WCP)	Cracked	60.00 F	*60.00 F
3	1		*FRONT BUMPER (WCP)	Buckled/Cracked	200.00 F	*200.00 F
4	1		*FRONT BUMPER SIDE RETAINER LH & RH (WCP)	N/s Cracked	50.00 F	*25.00 F
5	1		*FRONT BUMPER CENTRE GRILLE (WCP)	Cut	55.00 F	*55.00 F
6	1		*FRONT LH FOGLAMP GARNISH (WCP)	Serviceable	20.00 F	*- F
7	1		*FRONT LH FENDER (WCP)	Buckled	195.00 F	*195.00 F
8	1		*FRONT LH FENDER SHIELD (WCP)	Distorted	75.00 F	*75.00 F
9	1		*FRONT LH FENDER SIGNAL LIGHT (WCP)	Serviceable	20.00 F	*- F
10	1		*FRONT SHOCK ABSORBER LH & RH (WCP)	Serviceable	320.00 F	*- F
11	1		*FRONT ABSORBER MOUNTING LH & RH (WCP)	Serviceable	110.00 F	*- F
12	1		*FRONT ABSORBER DUST COVER LH & RH (WCP)	Serviceable	30.00 F	*- F
13	1		*FRONT ABSORBER STOPPER LH & RH (WCP)	Serviceable	24.00 F	*- F
14	1		*FRONT KNUCKLE ARM LH & RH (WCP)	N/s Bent/O/s Serviceable	320.00 F	*160.00 F
15	1		*FRONT WHEEL BEARING HUB LH & RH (WCP)	N/s Bent/O/s Serviceable	170.00 F	*85.00 F
16	1		*FRONT WHEEL BEARING LH & RH (WCP)	N/s Necessary/O/s Serviceable	90.00 F	*45.00 F
17	1		*FRONT LOWER ARM LH & RH (WCP)	Serviceable	150.00 F	*- F
18	1		*FRONT BALL JOINT LH & RH (WCP)	Serviceable	80.00 F	*- F
19	1		*STEERING RACK END LH & RH (WCP)	Serviceable	150.00 F	*- F
20	1		*TIE ROD END LH & RH (WCP)	Serviceable	100.00 F	*- F
21	1		*STEERING RACK (WCP)	Repair	900.00 F	*- F
22	1		*REAR AXLE (WCP)	Bent	700.00 F	*700.00 F
23	1		*REAR SHOCK ABSORBER LH & RH (WCP)	N/s Bent	170.00 F	*85.00 F
24	1		*REAR ABSORBER MOUNTING LH & RH (WCP)	N/s Bent	140.00 F	*70.00 F
25	1		*REAR ABSORBER DUST COVER LH & RH (WCP)	Serviceable	60.00 F	*- F
26	1		*REAR ABSORBER STOPPER LH & RH (WCP)	Serviceable	30.00 F	*- F
27	1		*REAR WHEEL BEARING HUB LH & RH (WCP)	N/s Bent/O/s Serviceable	470.00 F	*235.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REAR WHEEL BRAKE DRUM LH & RH (WCP)	Serviceable	260.00 F	*- F
29	1		*REAR BRAKE PUMP LH & RH (WCP)	Serviceable	120.00 F	*- F
30	1		*FRONT ABS SENSOR LH & RH (WCP)	Serviceable	310.00 F	*- F
31	1		*REAR BUMPER (WCP)	Buckled	230.00 F	*230.00 F
32	1		*REAR BUMPER SIDE RETAINER LH & RH (WCP)	N/s Distorted	60.00 F	*30.00 F
33	1		*REAR BUMPER REFLECTOR LH & RH (WCP)	Serviceable	50.00 F	*- F
34	1		*REAR RH LAMP (WCP)	Cracked	195.00 F	*195.00 F
35	1		*REAR LH LAMP (WCP)	Serviceable	195.00 F	*- F

F=Franchise part.

Sub Total (S\$)	6,429.00	2,765.00
+ Margin on L,N Items 10.00/10.00% (S\$)	642.90	276.50
Total Parts (S\$)	7,071.90	3,041.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT & REAR REVERSE SENSOR Frt Not Insured/Rear Serviceable	560.00	0.00
2	1	FRONT BUMPER CLIPS Necessary	35.00	35.00
3	1	FRONT FENDER SHIELD CLIPS Necessary	70.00	70.00
4	1	REAR BUMPER CLIPS Necessary	35.00	35.00
5	1	REAR FENDER SHIELD CLIPS Not Necessary	70.00	0.00
6	1	RIM 16 Dented	2,000.00	750.00
7	1	TYRE - 205/55/R16 (50%) Punctured	390.00	195.00
Sub Total (\$\$)			3,160.00	1,085.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT ON ALL AFFECTED AREA	New	1,000.00	800.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,200.00	600.00
3	TO CHECK WIRING SYSTEM & LIGHT	New	120.00	40.00
4	TO REMOVE/REFIX REAR AXLE, TYRE, RIM & UNDERCARRIAGE REPLACEMENT	New	280.00	200.00
5	TO REMOVE/REFIX FRONT TYRE, RIM & UNDERCARRIAGE REPLACEMENT	New	280.00	0.00
6	TO REMOVE/REFIX FRONT TYRE, RIM & UNDERCARRIAGE REPLACEMENT	New	180.00	0.00
7	WHEEL ALIGNMENT	New	100.00	100.00
Gross Labour Cost (\$\$)			3,160.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >