

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22001469/BVF3E2

Date: 16/04/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001960486
Claimant Vehicle No :	SJL4349L	Insured Vehicle No :	SLL740S
Date of Loss:	11/02/2022	Nature of Claim:	TP
		Claim No:	269736

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL4349L	Engine No:	4G18JS7307
Make & Model:	MITSUBISHI LANCER, 1.6 (A)	Chassis No:	JMYSTCS3A8U009696
Reg. Date:	27/11/2008 (Man. Year: 2008)	Odometer:	236479 km
Colour:	Blue		
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Firenza 4 mm	Rear Left Side:	Firenza 4 mm
Front Right Side:	Firenza 4 mm	Rear Right Side:	Firenza 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,354.29	15,729.97	4,624.32	22.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,320.00	5,440.00	4,880.00	47.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	30,674.29	21,169.97	9,504.32	30.98
Approved Total (Overridden) (\$\$)		10,700.00		
(\$\$)	30,674.29	10,700.00	19,974.29	65.12
+ GST 7.00/7.00% (\$\$)	2,147.20	749.00	1,398.20	65.12
Nett Amount (\$\$)	32,821.49	11,449.00	21,372.49	65.12

INSPECTION

Date of Assignment:	15/02/2022	
Date Inspected:	22/02/2022	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	21.0 days	

Adjuster: Lim Teow Guan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Apr 2022)
Parts:	143	MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL4349L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	663.90 FL	*557.00 FL
2	1		*BOOTLID LANCER EMBLEM	Necessary	28.00 FL	*28.00 FL
3	1		*BOOTLID CENTRE EMBLEM	Necessary	48.00 FL	*48.00 FL
4	1		*BOOTLID GLX EMBLEM	Necessary	24.00 FL	*24.00 FL
5	1		*BOOTLID NUMBER PLATE GARNISH	Broken	265.70 FL	*195.70 FL
6	1		*SET BOOTLID NUMBER PLATE GARNISH CLIPS	Necessary	60.00 FL	*20.00 FL
7	1		*BOOTLID RH HINGE	Bent	76.10 FL	*50.00 FL
8	1		*BOOTLID LH HINGE	Bent	76.10 FL	*50.00 FL
9	1		*BOOTLID LOCK	Jammed	78.00 FL	*78.00 FL
10	1		*BOOTLID LOCK CATCH	Bent	21.00 FL	*21.00 FL
11	1		*BOOTLID LOCK CABLE	Missing	97.00 FL	*40.00 FL
12	1		*BOOTLID WEATHERSTRIP	Torn	173.80 FL	*166.00 FL
13	1		*REAR BUMPER	Broken	689.00 FL	*689.00 FL
14	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FL	*30.00 FL
15	1		*REAR BUMPER BEAM	Bent	175.00 FL	*122.00 FL
16	1		*REAR BUMPER RH SIDE BEAM	Bent	46.00 FL	*46.00 FL
17	1		*REAR BUMPER LH SIDE BEAM	Bent	46.00 FL	*46.00 FL
18	1		*REAR WINDSCREEN GLASS RUBBER MOULDING	Necessary	34.00 FL	*34.00 FL
19	1		*REAR LH FENDER	Dented	684.00 FL	*684.00 FL
20	1		*REAR LH FENDER INNER TRIM	Torn	232.00 FL	*203.50 FL
21	1		*SET REAR LH FENDER INNER TRIM CLIPS	Necessary	50.00 FL	*20.00 FL
22	1		*REAR LH FENDER SPLASH SHIELD	Necessary	33.00 FL	*33.00 FL
23	1		*SET REAR LH FENDER SPLASH SHIELD CLIPS	Necessary	28.00 FL	*20.00 FL
24	1		*REAR RH FENDER	Dented	684.00 FL	*684.00 FL
25	1		*REAR RH FENDER INNER TRIM	Torn	232.00 FL	*203.50 FL
26	1		*SET REAR RH FENDER INNER TRIM CLIPS	Necessary	50.00 FL	*20.00 FL
27	1		*REAR RH FENDER SPLASH SHIELD	Necessary	33.00 FL	*33.00 FL
28	1		*SET REAR RH FENDER SPLASH SHIELD CLIPS	Necessary	28.00 FL	*20.00 FL
29	1		*RH TAILLAMP	Broken	513.00 FL	*489.20 FL
30	1		*RH TAILLAMP SPONGE GASKET	Necessary	21.00 FL	*21.00 FL
31	1		*SET RH TAILLAMP LOCK CLIPS	Necessary	23.00 FL	*12.00 FL
32	1		*RH TAILLAMP PANEL	Dented	176.00 FL	*155.00 FL
33	1		*LH TAILLAMP	Broken	513.00 FL	*489.20 FL
34	1		*LH TAILLAMP SPONGE GASKET	Necessary	21.00 FL	*21.00 FL
35	1		*SET LH TAILLAMP LOCK CLIPS	Necessary	23.00 FL	*12.00 FL
36	1		*LH TAILLAMP PANEL	Dented	176.00 FL	*155.00 FL
37	1		*END PANEL	Dented	583.00 FL	*407.00 FL
38	1		*END PANEL INNER GARNISH	Broken	178.00 FL	*135.00 FL
39	1		*SET END PANEL INNER GARNISH CLIPS	Necessary	50.00 FL	*30.00 FL
40	1		*SPARE TYRE PANEL	Dented	808.40 FL	*587.00 FL
41	1		*SPARE TYRE PANEL INNER INSULATOR	Necessary	178.00 FL	*150.00 FL
42	1		*SPARE TYRE TOP BOARD COVER	Broken	202.00 FL	*142.00 FL
43	1		*SPARE TYRE TOP BOARD COVER MAT	Not Necessary	195.40 FL	*- FL
44	1		*EXHAUST SILENCER	Dented	755.30 FL	*478.00 FL
45	1		*EXHAUST SILENCER GASKET	Necessary	34.00 FL	*34.00 FL
46	2		*EXHAUST SILENCER RUBBER HANGERS	Necessary	72.40 FL	*72.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*EXHAUST CENTRE PIPE	Bent	883.50 FL	*724.00 FL
48	1		*EXHAUST CENTRE PIPE GASKET	Necessary	34.00 FL	*34.00 FL
49	1		*REAR RH CHASSIS MEMBER	Bent	704.50 FL	*663.00 FL
50	1		*BONNET	Bent	667.00 FL	*629.00 FL
51	1		*BONNET RH HINGE	Bent	66.00 FL	*66.00 FL
52	1		*BONNET LH HINGE	Bent	66.00 FL	*66.00 FL
53	1		*BONNET LOCK	Jammed	55.00 FL	*55.00 FL
54	1		*BONNET LOCK CABLE	Missing	98.00 FL	*28.00 FL
55	1		*BONNET INNER RUBBER	Necessary	34.00 FL	*34.00 FL
56	1		*FRONT BUMPER	Broken	713.00 FL	*580.00 FL
57	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FL	*30.00 FL
58	1		*FRONT BUMPER REINFORCEMENT	Bent	155.00 FL	*155.00 FL
59	1		*FRONT BUMPER LOWER CENTRE GRILLE	Broken	78.00 FL	*78.00 FL
60	1		*FRONT BUMPER NUMBER PLATE HOLDER	Necessary	46.00 FL	*46.00 FL
61	1		*FRONT BUMPER RH SIDE RETAINER	Necessary	45.00 FL	*25.40 FL
62	1		*FRONT BUMPER LH SIDE RETAINER	Necessary	45.00 FL	*25.40 FL
63	1		*FRONT BUMPER RH FOG LAMP COVER	Broken	67.00 FL	*67.00 FL
64	1		*FRONT BUMPER LH FOG LAMP COVER	Not Necessary	67.00 FL	*- FL
65	1		*FRONT BUMPER LOWER COVER	Broken	145.00 FL	*145.00 FL
66	1		*SET FRONT BUMPER LOWER COVER CLIPS	Necessary	60.00 FL	*30.00 FL
67	1		*FRONT RH FENDER	Dented	487.00 FL	*487.00 FL
68	1		*FRONT RH FENDER SPLASH SHIELD	Torn	101.00 FL	*101.00 FL
69	1		*SET FRONT RH FENDER SPLASH SHIELD CLIPS	Necessary	60.00 FL	*30.00 FL
70	1		*FRONT LH FENDER	Not Damaged	487.00 FL	*- FL
71	1		*FRONT LH FENDER SPLASH SHIELD	Not Damaged	101.00 FL	*- FL
72	1		*SET FRONT LH FENDER SPLASH SHIELD CLIPS	Not Damaged	60.00 FL	*- FL
73	1		*FRONT GRILLE RH	Broken	93.00 FL	*93.00 FL
74	1		*SET FRONT GRILLE RH CLIPS	Necessary	25.00 FL	*10.00 FL
75	1		*FRONT GRILLE LH	Broken	93.00 FL	*93.00 FL
76	1		*SET FRONT GRILLE LH CLIPS	Necessary	25.00 FL	*10.00 FL
77	1		*FRONT GRILLE HOLDER	Necessary	167.00 FL	*167.00 FL
78	1		*FRONT GRILLE EMBLEM	Necessary	42.00 FL	*32.00 FL
79	1		*HEADLAMP LH	Broken	488.00 FL	*488.00 FL
80	1		*HEADLAMP LH LOCK CLIPS	Necessary	5.00 FL	*5.00 FL
81	1		*HEADLAMP RH	Broken	488.00 FL	*488.00 FL
82	1		*HEADLAMP RH LOCK CLIPS	Necessary	5.00 FL	*5.00 FL
83	1		*FRONT HORN	Short Circuit	78.00 FL	*45.00 FL
84	1		*SUPPORT PANEL	Dented	608.00 FL	*400.00 FL
85	1		*FRONT AIR DUCT	Broken	96.00 FL	*82.00 FL
86	1		*FRONT BATTERY TRAY	Not Damaged	27.00 FL	*- FL
87	1		*FRONT BATTERY COVER	Not Damaged	28.00 FL	*- FL
88	1		*FRONT WIPER TANK	Broken	88.00 FL	*88.00 FL
89	1		*AIRCON CONDENSER	Broken	1,016.00 FL	*773.00 FL
90	1		*AIRCON LIQUID PIPE	Bent	202.00 FL	*105.00 FL
91	1		*AIRCON SUCTION PIPE	Bent	198.00 FL	*165.00 FL
92	1		*AIRCON DISCHARGE PIPE	Bent	187.00 FL	*187.00 FL
93	1		*AIRCON FAN ASSY	Broken	868.00 FL	*818.00 FL
94	1		*RADIATOR ASSY	Broken	898.00 FL	*802.00 FL
95	1		*RADIATOR UPPER HOSE	Necessary	78.00 FL	*28.00 FL
96	1		*RADIATOR LOWER HOSE	Necessary	84.00 FL	*39.00 FL
97	1		*RADIATOR FAN ASSY	Broken	868.00 FL	*306.00 FL
98	1		*BOOTLID C&C EMBLEM	Necessary	85.00 FS	*35.00 FS
99	1		*REAR NUMBER PLATE	Not Damaged	70.00 FS	*- FS
100	1		*SET REAR BUMPER RH SIDE BEAM RIVETS	Necessary	35.00 FS	*20.00 FS
101	1		*SET REAR BUMPER LH SIDE BEAM RIVETS	Necessary	35.00 FS	*20.00 FS
102	1		*SET REAR BUMPER REVERSE SENSOR	Short Circuit	280.00 FS	*200.00 FS
103	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*30.00 FS
104	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*20.00 FS
105	1		*END PANEL JOINT SEALANT	Necessary	70.00 FS	*40.00 FS
106	1		*REAR RH FENDER JOINT SEALANT	Necessary	70.00 FS	*20.00 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
107	1		*REAR LH FENDER JOINT SEALANT	Necessary	70.00 FS	*20.00 FS
108	1		*SPARE TYRE PANEL JOINT SEALANT	Necessary	70.00 FS	*40.00 FS
109	1		*REAR RH CHASSIS MEMBER JOINT SEALANT	Necessary	70.00 FS	*20.00 FS
110	1		*FRONT NUMBER PLATE	Missing	70.00 FS	*30.00 FS
111	1		*RADIATOR COOLANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,493.10	17,418.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,138.81	1,688.33

Total Parts (\$\$)	20,354.29	15,729.97
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND REALIGN ALL AFFECTED PANELS AND AREAS (REAR)	New	3,000.00	1,400.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS (REAR)	New	1,800.00	1,200.00
3	CHECK WIRING AND LIGHTING SYSTEM (REAR)	New	80.00	30.00
4	REMOVE AND REINSTALL REAR WINDSCREEN GLASS TO ASSIST REPAIR (REAR)	New	200.00	120.00
5	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR (REAR)	New	70.00	60.00
6	REMOVE AND REPLACE REAR INNER TRIM, GARNISH, BOARDS, ROOF LINING, SEATS AND CARPET TO ASSIST REPAIR (REAR)	New	450.00	250.00
7	REMOVE AND REINSTAL FUEL TANK, PIPES AND SENSORS TO ASSIST REPAIR (REAR)	New	120.00	0.00
8	REMOVE AND REPLACE EXHAUST SILENCER, CENTRE PIPE AND GASKETS TO ASSIST REPAIR (REAR)	New	220.00	80.00
9	MOUNT VEHICLE ON CHASSIS ALIGNMENT BENCH TO REPAIR BOTH CHASSIS FRAME AND MEMBERS (REAR)	New	550.00	250.00
10	REMOVE AND REINSTALL REAR UNDERCARRIAGE PARTS TO ASSIST REPAIR (REAR)	New	450.00	0.00
11	TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM (REAR)	New	100.00	0.00
12	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND REALIGN ALL AFFECTED PANELS AND AREAS (FRONT)	New	1,200.00	800.00
13	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS (FRONT)	New	80.00	0.00
14	REMOVE AND REPLACE AIRCON CONDENSER AND PIPES TO ASSIST REPAIR. TO REFILL AIRCON GAS (FRONT)	New	200.00	120.00
15	REMOVE AND REPLACE RADIATOR ASSY, HOSES AND FAN ASSY TO ASSIST REPAIR. TO REFILL COOLANT (FRONT)	New	200.00	100.00
16	REFOCUS AND ADJUST HEADLAMPS ASSY (FRONT)	New	60.00	0.00
17	CHECK WIRING AND LIGHTING SYSTEM (FRONT)	New	60.00	30.00
18	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS (REAR)	New	180.00	0.00
19	SPRAY PAINTING ON AFFECTED AREAS AND PANELS (FRONT)	New	1,300.00	1,000.00
Gross Labour Cost (\$\$)			10,320.00	5,440.00

Report was unsubmitted during this print-out.