

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001472/KTY3Q2**Date:** 22/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00004222101

Claimant Vehicle No : SMN9612Y **Insured Vehicle No :** SMQ1004P

Date of Loss: 14/02/2022 Nature of Claim: TP Claim No: SNM22D201114/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN9612Y**

Make & Model: HONDA VEZEL HYBRID, 1.5 x (A) Engine No: LEB6744736

Reg. Date: 03/09/2019 (Man. Year: 2018) Chassis No: RU31324724

Colour: Metallic Dark Blue Odometer: 162742 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: INTERTRAC 3 mm Rear Left Side: SUNWIDE 2 mm

Front Right Side: INTERTRAC 3 mm Rear Right Side: SUNWIDE 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,376.64	816.64	4,560.00	84.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,030.00	610.00	1,420.00	69.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,406.64	1,426.64	5,980.00	80.74
Approved Total (Overridden) (\$\$)		1,150.00		
(\$\$)	7,406.64	1,150.00	6,256.64	84.47
+ GST 7.00/7.00% (\$\$)	518.46	80.50	437.96	84.47
Nett Amount (\$\$)	7,925.10	1,230.50	6,694.60	84.47

INSPECTION

Date of Assignment: 15/02/2022

Date Inspected: 16/02/2022 Inspected At: Optima Werkz Pte Ltd (HQ)
10 Ang Mo Kio Industrial Park 2A, #01-05 AMK
Autopoint
Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Apr 2022)
Parts:	M1-SUV	HONDA VEZEL HYBRID 1.5 x (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN9612Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP LH	Serviceable	1,723.50 FL	*- FL
2	1		*FRONT HEADLAMP LOWER BRACKET LH	Serviceable	55.60 FL	*- FL
3	1		*FRONT BUMPER	Mtg Cracked	817.90 FL	*762.70 FL
4	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	33.90 FL	*- FL
5	1		*FRONT FENDER LH	Repair	548.60 FL	*- FL
6	1		*FRONT FENDER HYBRID EMBLEM LH	Necessary	57.40 FL	*57.40 FL
7	1		*FRONT FENDER INNER SHIELD LH	Serviceable	134.60 FL	*- FL
8	1		*FRONT WHEEL ARCH GARNISH LH	Dented /Cut	175.70 FL	*175.70 FL
9	1		*FRONT ALLOY RIM LH	Serviceable	1,650.00 FL	*- FL
10	1		*FRONT SHOCK ABSORBER LH	Serviceable	351.50 FL	*- FL
11	1		*FRONT KNUCKLE ARM LH	Serviceable	243.50 FL	*- FL
12	1		*FRONT WHEEL BEARING LH	Serviceable	152.10 FL	*- FL
13	1		*FRONT LOWER ARM LH	Serviceable	351.50 FL	*- FL
14	1		*FRONT DOOR SIDE MIRROR COVER LH (NPA)	Repair	0.00 FL	*- FL
15	1		*FRONT DOOR LH (NPA)	Repair	0.00 FL	*- FL
16	1		*FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
17	1		*FRONT FENDER INNER SHIELD CLIPS LH	Not Necessary	20.00 FS	*- FS
18	1		*FRONT TYRE LH -215/60 R16	Serviceable	250.00 FS	*- FS
19	1		*FRONT WHEEL ARCH GARNISH CLIPS LH	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,635.80	1,015.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,259.16	199.16
Total Parts (\$\$)	5,376.64	816.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE REPLACE REPAIR REFIX & READJUST LEFT ACCIDENT AREAS & ETC	New	700.00	200.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREAS & ETC	New	700.00	400.00
3	TO TUFF KOTE & UNDERSEAL MATERIALS	New	100.00	0.00
4	TO WHEEL ALIGNMENT & BALANCING	New	100.00	0.00
5	TO DAIGNOSIS FAULT CODE & RESET MEMORY	New	100.00	0.00
6	LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER LH ,FRONT KNUCKLE ARM LH ,FRONT LOWER ARM LH & ETC	New	250.00	0.00
7	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	10.00
Gross Labour Cost (\$\$)			2,030.00	610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >