

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001473/ATY3N2**Date:** 08/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00043282100

Claimant Vehicle No : SLZ5174U **Insured Vehicle No :** SMW2910K

Date of Loss: 14/02/2022 Nature of Claim: TP Claim No: SNM22D201116/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ5174U**

Make & Model: HONDA FREED, 1.5 G (A) Engine No: LEB5580922

Reg. Date: 07/05/2018 (Man. Year: 2017) Chassis No: GB71051090

Colour: Blue Odometer: 181642 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65R15 Rear Tyre Size: 185/65R15

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,356.70	1,762.32	3,594.38	67.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,270.00	1,190.00	1,080.00	47.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,626.70	2,952.32	4,674.38	61.29
Approved Total (Overridden) (\$\$)		2,350.00		
Nett Amount (\$\$)	7,626.70	2,350.00	5,276.70	69.19

INSPECTION

Date of Assignment: 15/02/2022

Date Inspected: 16/02/2022 Inspected At: Automobile Hub Enterprise
1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Mar 2022)
Parts:	M1-MPV	HONDA FREED 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ5174U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH FENDER	Dented	440.70 F	*440.70 FL
2	1		*FRONT LH FENDER INNER SHIELD	Deformed	155.90 F	*155.90 FL
3	1		*FRONT LH FENDER HYBRID EMBLEM	Necessary	55.90 F	*55.90 FL
4	1		*FRONT LH DOOR	Dented	950.40 F	*950.40 FL
5	1		*FRONT LH DOOR LOCK	Not Necessary	262.30 F	*- FL
6	1		*FRONT LH DOOR WEATHERSTRIPE	Not Necessary	210.80 F	*- FL
7	2		*FRONT LH DOOR HINGE	Not Necessary	194.40 F	*- FL
8	1		*FRONT LH LOWER ARM	Not Necessary	352.00 F	*- FL
9	1		*FRONT LH SHOCK ABSORBER	Not Necessary	358.40 F	*- FL
10	1		*FRONT LH KNUCKLE ARM	Not Necessary	425.60 F	*- FL
11	1		*FRONT LH WHEEL HUB C/W BEARING	Not Necessary	280.10 F	*- FL
12	1		*FRONT LH WING MIRROR	Repair	680.20 F	*- FL
13	1		*FRONT LH FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
14	1		*FRONT LH WHEEL RIM	Cut	680.00 FS	*450.00 FS
15	1		*FRONT LH TYRE	Not Necessary	280.00 FS	*- FS
					Sub Total (\$\$)	
					5,356.70	2,082.90
					- List Item Discount on L Items 0.00/20.00% (\$\$)	
					0.00	320.58
					Total Parts (\$\$)	
					5,356.70	1,762.32

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	500.00
2	SPRAY PAINTING	New	800.00	500.00
3	WIRING	New	50.00	30.00
4	TO TRANSFER DOOR FITTINGS	New	150.00	80.00
5	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
6	TO DISMANTLE FRONT UNDERCARRIAGE	New	320.00	0.00
Gross Labour Cost (S\$)			2,270.00	1,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >