12/29/22, 3:09 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG22001481/APA3Q2

29/12/2022 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100071077 **Claimant Vehicle** SKZ6108S Insured Vehicle No: SDW818P

No:

Date of Loss: 26/01/2022 Nature of Claim: TP Claim No: 5890945874SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKZ6108S

NISSAN X-TRAIL, 2.0 CVT ABS 4WD S/R 7-STR Engine No: Make & Model:

MR20703818B (A)

Reg. Date: 28/01/2016 (Man. Year: 2015) JN1JANT32Z0000325 Chassis No:

Colour: Black Odometer: 68551 km

1997 cc **Engine Capacity:** Market Value/New Car N/A

Price:

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): **Engine Modification:** Yes No

CONDITION OF TYRES

225/60 R18 Front Tyre Size: 225/60 R18 Rear Tyre Size: Front Left Side: Rear Left Side: Yokohama 6 mm Yokohama 6 mm Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,498.30	931.70	566.60	37.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	600.00	400.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,498.30	1,531.70	966.60	38.69
Approved Total (Overridden) (S\$)		1,200.00		
(S\$)	2,498.30	1,200.00	1,298.30	51.97
+ GST 7.00/7.00% (S\$)	174.88	84.00	90.88	51.97
Nett Amount (S\$)	2,673.18	1,284.00	1,389.18	51.97
+ Car Rental (3.0 x S\$	130.00/day) (S\$)	390.00		
N	ett Liability (S\$)	1,674.00		
Global Sum	Settlement (S\$)	1,650.00		

INSPECTION

Date of Assignment: 14/02/2022

J-mart Motor Pte Ltd (HQ) Date Inspected: 14/02/2022 Inspected At: Blk 5 Defu Lane 10, #01-578

Singapore 539186

Estimated Period of Repair: 3.0 days

ADRIAN LING Adjuster: Manager: **CHEW HSIAO TONG** NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	793.00 FN	*793.00 FN
2	1		*REAR BUMPER LOWER COVER	Not Necessary	94.00 FN	*- FN
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	480.00 FN	*- FN
4	1		*REAR BUMPER CLIPS (24 PCS)	Necessary	20.00 FN	*20.00 FN
5 E=Ers	1	nart S=SncNe	*REVERSE SENSOR tt. N=NettItemDisc.	Damaged	250.00 FS	*200.00 FS
1 -1 16	inomise	part. 0-operie	a. N-Netheribise.	Sub Total (S\$)	1,637.00	1,013.00
			- Nett Item Discount on N Items 10.00/10.00% (S\$)			81.30
				Total Parts (S\$)	1,498.30	931.70
			Report was unsubmitted durir	na this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
Lab	our Items					
1	PANEL BEATING	New	500.00	200.00		
2	SPRAY PAINTING	New	500.00	400.00		
		Gross Labour Cost (S\$)	1,000.00	600.00		
Report was unsubmitted during this print-out.						

< END OF ESTIMATES >