



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 2054R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT DOOR O/S	TO REPAIR SEE LABOUR	950.00	-
1	FRONT DOOR "K2500" STICKER O/S	NECESSARY	120.00	80.00
1	FRONT DOOR MIRROR ASSY O/S	BROKEN	680.00	390.00
1	FRONT CORNER PANEL O/S	TO REPAIR SEE LABOUR	380.00	-
1	HEADLAMP O/S	CRACKED	750.00	450.00
1	FRONT BUMPER	GRAZED	745.00	455.00
1	SET FRONT DOOR "ROC" STICKER O/S	NECESSARY	50.00	50.00
1	REAR CARGO BOX FRONT PANEL O/S (DENTED)	NOT CONSISTENT WITH THE IMPACT	1,200.00	-
	LESS 10% DISCOUNT		-	-142.50
			4,875.00	1,282.50
<u>LABOUR</u>				
	TO CHECK WIRING.		50.00	20.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	50.00	-
	TO TRANSFER FRONT DOOR MECHANISM.	NOT NECESSARY	80.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT DOOR O/S AND FRONT CORNER PANEL O/S.		600.00	400.00
	TO PUTTY & SPRAY PAINTING.		750.00	300.00
			1,530.00	720.00
GRAND TOTAL			6,405.00	2,002.50

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,600.00
---	--	--	-----------------

Report Ref No. CS/SMO22001484/Utf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.