

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III21003985/RTF3E2-1

Date: 03/03/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_01

Claimant Vehicle No : SBW3363M **Insured Vehicle No :** GBK2234Y

Date of Loss: 26/03/2021 Nature of Claim: TP Claim No: MFL2021D0001326

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBW3363M**
Make & Model: MERCEDES-BENZ A200, 1.3 (A) Engine No: 28291480091236
Reg. Date: 10/04/2019 (Man. Year: 2019) Chassis No: WDD1770872J075992
Colour: White Odometer: 26948 km
Engine Capacity: 1332 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,910.19	3,433.44	6,476.75	65.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,240.00	1,190.00	1,050.00	46.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,150.19	4,623.44	7,526.75	61.95
Approved Total (Overridden) (S\$)		3,700.00		
(S\$)	12,150.19	3,700.00	8,450.19	69.55
+ GST 7.00/7.00% (S\$)	850.51	259.00	591.51	69.55
Nett Amount (S\$)	13,000.70	3,959.00	9,041.70	69.55

INSPECTION

Date of Assignment: 16/02/2022

Date Inspected: 29/03/2021 Inspected At: Garage 13 Pte Ltd (HQ)
8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #03-46
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Mar 2022)
Parts:	144	MERCEDES-BENZ A200 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBW3363M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,598.80 FL	*1,450.00 FL
2	1		*REAR BUMPER LOWER LID	Broken	589.50 FL	*277.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Bent	655.00 FL	*410.00 FL
4	1		*REAR BUMPER INNER GUIDE RAIL	Damaged	215.80 FL	*215.80 FL
5	1		*REAR BUMPER LOWER BEAM	Not Necessary	144.00 FL	*- FL
6	2		*REAR BUMPER SIDE BRACKET	Not Necessary	250.00 FL	*- FL
7	1		*REAR BUMPER SIDE LOWER GARNISH LH	Deformed	108.90 FL	*108.90 FL
8	1		*REAR BUMPER LOWER CHROME MOULDING	Broken / Torn	278.90 FL	*278.90 FL
9	1		*REAR BUMPER REFLECTOR	N/S Damaged / O/S Refix	205.00 FL	*48.00 FL
10	1		*TAIL LAMP	N/S Cracked / O/S Reuse	1,230.40 FL	*587.00 FL
11	1		*TAIL LAMP BRACKET LH	Cracked	95.00 FL	*84.00 FL
12	1		*REAR END PANEL	Repair	689.40 FL	*- FL
13	1		*REAR END PANEL TOP GARNISH	Reuse	248.00 FL	*- FL
14	1		*REAR BUMPER REVERSE SENSOR (6PCS)	Damaged (1Pc Only)	1,405.20 FL	*195.00 FL
15	1		*TAILGATE	Repair	2,154.50 FL	*- FL
16	1		*TAILGATE WEATHERSTRIP	Not Necessary	211.00 FL	*- FL
17	1		*TAILGATE LOGO	Necessary	85.90 FL	*69.00 FL
18	1		*TAILGATE EMBLEM A200	Necessary	65.00 FL	*58.00 FL
19	1		*TAILGATE LOCK	Serviceable	358.80 FL	*- FL
20	10		*REAR BUMPER CLIPS	Necessary	55.00 FS	*30.00 FS
21	1		*REAR END PANEL SEALANT	Not Necessary	40.00 FS	*- FS
22	1		*TAILGATE WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
23	1		*REAR EXHAUST CHROME RIM LH	Not Necessary	225.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,969.10	3,811.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,058.91	378.16
Total Parts (\$\$)	9,910.19	3,433.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE PARTS REPAIR COLUMN INCLUSIVE OF REPLACEMENT PARTS	New	855.00	500.00
2	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL	New	950.00	600.00
3	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	30.00	0.00
4	REMOVE AND REFIX TAILGATE REAR WINDSCREEN GLASS. (2-MAN JOB)	New	157.50	0.00
5	REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR & CONDUCT DISTANCE SAFETY SETTING	New	76.50	60.00
6	CONDUCT WATER LEAK TEST FOR REAR PORTION ASSOCIATED REPAIR WORKS	New	45.00	0.00
7	TRANSFER OF EXISTING TAILGATE MECHANISM TO NEW TAILGATE	New	90.00	0.00
8	WIRING / BULB CHECKING (INCLUSIVE OF RE-FOCUS / RE-ADJUST ON ANGLE OF LIGHT INTENSITY)	New	36.00	30.00
Gross Labour Cost (\$\$)			2,240.00	1,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >